

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

AUG 07 2020

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corp.	API Number 30025065290000
Property Name EAST BLUEBRY DRINKING UNIT	Well No. 23

Surface Location									
UL - Lot	Section	Township	Range		Feet from	NS Line	Feet from	EAV Line	County
	11	21	37						LEA

Well Status									
YES	TAD WELL	YES	SHUT-IN	YES	INJECTOR	SWD	OIL	PRODUCER	GAS
	☒		☒		☒				
									DATE 5-22-20

OBSERVED DATA

	(A) Surface	(B) Hole #1	(C) Intern #1	(D) Prod. Cms	(E) Tubing
Pressure	☒	☒		35	1645
Flow Characteristics					
Puff	☒ Y/N	☒ Y/N	Y/N	☒ Y/N	CO2 WTR ☒ GAS ☐ Type of fluid injected for Workover if applies
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	☒ Y/N	☒ Y/N	Y/N	☒ Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature Albert Rodriguez		OIL CONSERVATION DIVISION	
Printed name: ALBERT RODRIGUEZ		Entered into RBDMS	
Title Mechanic		Re-test	
E-mail Address:			
Date: 5-22-20	Phone: 432-425-2963		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM