

HOBBS OCD

AUG 07 2020

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Co2		API Number 30025065560000	
Property Name East Dineen Dry Sinkhole Unit		Well No. 37	

Surface Location									
UL - Lot	Section	Township	Range		Feet from	NS Line	Feet from	EAV Line	County
	13	21	37						Lea

Well Status										
TA'D WELL	YES	NO	SHUT-IN	YES	NO	INJECTOR	SWD	PRODUCER	GAS	DATE
		NO			NO	INJ				6-26-20

OBSERVED DATA

	(A) Surface	(B) Interval (1)	(C) Interval (2)	(D) Prod Cms	(E) Tubing
Pressure	20	20		20	20
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

CO2
 WTR ☒
 GAS ☐
 Type of fluid
 referred for
 Waterflood if
 applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature Albert Rodriguez		OIL CONSERVATION DIVISION	
Printed name Albert Rodriguez		Entered into RBDMS	
Title Mechanic		Re-test	
E-mail Address			
Date 6-26-20	Phone 432-425-2963		
Witness			

INSTRUCTIONS ON BACK OF THIS FORM