

HOBBES OGD

AUG 07 2020

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corp.		APT Number 30025065660000	
Property Name East Blueberry Driveland Unit		Well No. 53	

Surface Location

UL - Lot	Section	Township	Range	Feet from	NS Line	Feet from	EAV Line	County
	13	21	37					LEA

Well Status

TA'D WELL	YES	NO	SHUT-IN	YES	NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
												3-19-20

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Cms	(E) Tubing
Pressure	20			0	1658
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood or other
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature Albert Rodriguez		OIL CONSERVATION DIVISION	
Printed name ALBERT RODRIGUEZ		Entered into RBDMS	
Title Mechanic		Re-test X	
E-mail Address			
Date 3-19-20	Phone 432-425-2963		
Witness			

INSTRUCTIONS ON BACK OF THIS FORM