

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 18 2020

BRADENHEAD TEST REPORT

RECEIVED

Operator Name <u>Apache Oil Corp.</u>	API Number <u>30-025-06340</u>
Property Name <u>North East Drinkard Unit (NEDU)</u>	Well No. <u>115</u>

1. Surface Location

UT - Lot <u>E</u>	Section <u>21S</u>	Township <u>37E</u>	Range <u>5940</u>	Feet from <u>S</u>	N/S Line <u>660</u>	Feet from <u>W</u>	E/W Line <u>Leq</u>	County <u>Leq</u>
----------------------	-----------------------	------------------------	----------------------	-----------------------	------------------------	-----------------------	------------------------	----------------------

Well Status

TA'D WELL YES ☒ NO ☐	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ SWD ☐	PRODUCER OIL ☐ GAS ☐	DATE <u>2-21-20</u>
--	--	--	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<u>Ø</u>	<u>—</u>	<u>—</u>	<u>Ø</u>	<u>Ø</u>
Flow Characteristics					
Puff	☒ N	Y / N	Y / N	☒ N	CO2 <u>—</u>
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS <u>—</u>
Down to nothing	☒ Y / N	Y / N	Y / N	☒ Y / N	Type of fluid Injected for Water flow if applies
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Down for Line repair

Signature: <u>Tracy Cole</u>	OIL CONSERVATION DIVISION
Printed name: <u>Tracy Cole</u>	Entered into RBDMS
Title:	Re-test <u>X X</u>
E-mail Address:	
Date:	Phone: <u>575-441-5196</u>
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM