

AUG 18 2020

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Oil Corp.		API Number 30-025-06354	
Property Name North East Drinkard Unit (NEDU)		Well No. 121	

1. Surface Location

UL - Lot G	Section 2	Township 21S	Range 37E	Feet from 2220	N/S Line N	Feet From 2307	E/W Line E	County Lea
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

YES	TA'D WELL (NO)	YES	SHUT-IN (NO)	(INJ)	INJECTOR SWD	OIL	PRODUCER GAS	DATE 2-22-20
-----	--------------------------	-----	------------------------	--------------	-----------------	-----	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø	Ø	Ø	Ø	1200
Flow Characteristics					
Puff	Y / (N)	Y / (N)	(Y) N	(Y) N	CO2 —
Steady Flow	Y / (N)	Y / (N)	Y / (N)	Y / (N)	WTR ✓
Surges	Y / (N)	Y / (N)	Y / (N)	Y / (N)	GAS —
Down to nothing	Y / N	Y / N	(Y) N	(Y) N	Type of Fluid
Gas or Oil	Y / (N)	Y / (N)	Y / (N)	Y / (N)	Injected for
Water	Y / (N)	Y / (N)	Y / (N)	Y / (N)	Waterflow if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Tracy Cole		OIL CONSERVATION DIVISION	
Printed name: Tracy Cole		Entered into RBDMS	
Title:		Rc-test	
E-mail Address:		X	
Date:	Phone: 575-441-5196		
Witness:			