

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 18 2020

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <u>Apache Oil Corp.</u>		API Number <u>30-025-06453</u>
Property Name <u>North East Drinkard Unit (NEDU)</u>		Well No. <u>410</u>

1. Surface Location

UT. - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
<u>H</u>	<u>10</u>	<u>21S</u>	<u>37E</u>	<u>1980</u>	<u>N</u>	<u>660</u>	<u>E</u>	<u>Leq</u>

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	☒ INJ	SWD	PRODUCER OIL	GAS	DATE <u>5-21-20</u>
------------------	-------------------------------------	----------------	-------------------------------------	--------------------------------------	-----	-----------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	<u>Ø</u>	<u>—</u>	<u>—</u>	<u>Ø</u>	<u>1215</u>
Flow Characteristics					
Puff	☒ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	☒ Y / ☐ N	CO2 <u>—</u>
Steady Flow	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☒ N	WTR <u>✓</u>
Surges	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☒ N	GAS <u>—</u>
Down to nothing	☒ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	☒ Y / ☐ N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☒ N	
Water	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <u>Tracy Cole</u>		OIL CONSERVATION DIVISION	
Printed name: <u>Tracy Cole</u>		Entered into RBDMS	
Title:		Re-test <u>X</u>	
E-mail Address:			
Date:	Phone: <u>575-441-5196</u>		
	Witness:		

INSTRUCTIONS ON BACK OF THIS FORM