

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 18 2020

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Oil Corp.		API Number 30-025-35904
Property Name North East Drinkard Unit (NEDU)		Well No. 240

7. Surface Location

UT. - Lot M	Section 3	Township 21S	Range 37E	Feet from 3450	N/S Line S	Feet From 660	E/W Line W	County Lea
-----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	☒ INJ	INJECTOR SWD	OIL PRODUCER	GAS	DATE 5-12-20
------------------	-------------------------------------	----------------	-------------------------------------	--------------------------------------	-----------------	-----------------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	☒	—	—	☒	1160
Flow Characteristics					
Pull	Y / ☒ N	Y / N	Y / N	Y / ☒ N	CO2 —
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS —
Down to nothing	☒ Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Tracy Cole		OIL CONSERVATION DIVISION	
Printed name: Tracy Cole		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone: 575-441-5196		
	Witness:		

INSTRUCTIONS ON BACK OF THIS FORM