

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

SEP 01 2020

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Apache Corporation		API Number API 300-253 7211	
Property Name Sunflower 3 #1		Well No. 1	

2. Surface Location									
UL - Lot D	Section 03	Township 185	Range 34 E		Feet from 1070'	N/S Line FNL	Feet From 1220'	E/W Line FWL	County Lea

Well Status										
YES	TA'D WELL (NO)	YES	SHUT-IN (NO)	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 8/26/20

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	0		75 psi	75 psi
Flow Characteristics					
Puff	Y / (N)	Y / (N)	Y / N	Y / N	CO2 —
Steady Flow	Y / (N)	Y / (N)	Y / N	Y / N	WTR —
Surges	Y / (N)	Y / (N)	Y / N	Y / N	GAS —
Down to nothing	(Y) N	(Y) N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / (N)	Y / (N)	Y / N	Y / N	
Water	Y / (N)	Y / (N)	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name: Albert De la Cruz		Entered into RBDMS	
Title: Pumper		Re-test	
E-mail Address: albert.de.la.cruz@apache corp. com		72	
Date: 8/26/20	Phone:		
	Witness:		