Submit One Copy To Appropriate District State of New Mexico	Form C-103
Office District I 1625 N. French Dr., Hobbs, NM 88240 District II	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 811 S. First St., Artesia, NM 88210 District III	30-025-25225
District III SEP 1 9200 SEP 1 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe NM 87505	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505 <b>RECEIVED</b> Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	SFPRR
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Well Number 16
1. Type of Well: Oil Well Gas Well Other	
2. Name of Operator	9. OGRID Number
Rover Operating LLC.	371484
3. Address of Operator	10. Pool name or Wildcat
17304 Preston Rd. Suite 300, Dallas, TX, 75252	Sawyer San Andres West
4. Well Location	• · · · · · · · · · · · · · · · · · · ·
Unit Letter <u>E</u> : <u>1980</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u> line	
Section <u>34</u> Township <u>9S</u> Range <u>37E</u> NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3967' GR	
2. Check Appropriate Box to Indicate Nature of Notice, Report or Other Da	ta
	SEQUENT REPORT OF:
PULL OR ALTER CASING  MULTIPLE COMPL CASING/CEMENT	ГЈОВ 🔲
OTHER:	eady for OCD Inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Opera	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR DERMANENTLY STAMPED ON THE MADVED'S SUBFACE	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	All fluids have been removed from non
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
······································	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
and in	
SIGNATUREPetroleum E	EngineerDATE9/18/20
TYPE OR PRINT NAMEZach Dyer E-MAIL:zdyer@roverpetro.com PHONE: _214-234-9115	
For State Use Only	
APPROVED BY: Kerry Futz TITLE COA	DATE 9-18-20