

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-37696
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: William Turner
8. Well Number 10
9. OGRID Number 14021
10. Pool name or Wildcat Penrose Skelly Grayburg (50350)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other
2. Name of Operator Marathon Oil Company
3. Address of Operator P.O. Box 3487 Houston, TX 77253-3487
4. Well Location Unit Letter <u>I</u> : <u>1783'</u> feet from the <u>South</u> line and <u>895'</u> feet from the <u>East</u> line Section <u>29</u> Township <u>21-S</u> Range <u>37-E</u> NMPM County <u>Lea</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>3472' GR</u>
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☒
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

This sundry is being sent to correct the production casing sundry dated 05/04/2006 for the William Turner No. 10. The original sundry noted that on 03/29/2006 the production casing was cemented w/ 750 sks Interfill "C". This was the lead cement for the production casing. The tail cement pumped in addition to this 750 sks was 300 sks Premium Plus cement w/ 15.6 density, 1.19 cuft/sk yield, 5.15 gals water / sk which was then displaced w/ the 19 bbls 10% MSA acid.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Charles E. Kendrix TITLE Regulatory Compliance Rep DATE 05/11/2006
Type or print name Charles E. Kendrix E-mail address: cekendrix@marathonoil.com
Telephone No. 713-296-2096

For State Use Only

APPROVED BY [Signature] TITLE PETROLEUM ENGINEER DATE MAY 18 2006
Conditions of Approval, if any: