

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-144  
June 1, 2004

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

For drilling and production facilities, submit to appropriate NMOCD District Office.  
For downstream facilities, submit to Santa Fe office

**Pit or Below-Grade Tank Registration or Closure**

Is pit or below-grade tank covered by a "general plan"? Yes ☐ No ☒

Type of action: Registration of a pit or below-grade tank ☐ Closure of a pit or below-grade tank ☒

Operator: <u>CHESAPEAKE OPERATING, INC.</u> Telephone: <u>432-687-2992</u> e-mail address: <u>SSTRICKLIN@CHKENERGY.COM</u>		
Address: <u>P. O. BOX 11050 MIDLAND, TEXAS 79702-8050</u>		
Facility or well name: <u>KF 4 STATE WELL #001</u>	API #: <u>30-025-37129</u>	U/L or Qtr/Qtr <u>X</u> Sec <u>4</u> T <u>21S</u> R <u>35E</u>
County: <u>LEA</u>	Latitude _____	Longitude _____ NAD: 1927 <input type="checkbox"/> 1983 <input type="checkbox"/>
Surface Owner: Federal <input type="checkbox"/> State <input type="checkbox"/> Private <input checked="" type="checkbox"/> Indian <input type="checkbox"/>		
<b>Pit</b> Type: Drilling <input checked="" type="checkbox"/> Production <input type="checkbox"/> Disposal <input type="checkbox"/> Workover <input type="checkbox"/> Emergency <input type="checkbox"/> Lined <input checked="" type="checkbox"/> Unlined <input type="checkbox"/> Liner type: Synthetic <input checked="" type="checkbox"/> Thickness <u>12</u> mil Clay <input type="checkbox"/> Pit Volume <u>12,139</u> bbl	<b>Below-grade tank</b> Volume: _____ bbl Type of fluid: _____ Construction material: _____ Double-walled, with leak detection? Yes <input type="checkbox"/> If not, explain why not. _____	
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.) <u>89'+</u>	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) (10 points) ( 0 points) 0
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) ( 0 points) 0
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) ( 0 points) 0
<b>Ranking Score (Total Points)</b>		0

**If this is a pit closure:** (1) Attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if you are burying in place) onsite ☒ offsite ☐ If offsite, name of facility \_\_\_\_\_. (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No ☒ Yes ☐ If yes, show depth below ground surface \_\_\_\_\_ ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavations.

Additional Comments:
A SIDE DEEP BURIAL TRENCH WAS EXCAVATED NEXT TO THE PIT. THE TRENCH WAS LINED WITH A 20 MIL SYNTHETIC LINER. THE PIT CONTENTS WERE THEN PLACED INTO THE LINED TRENCH. THE SIDES OF THE TRENCH WERE FOLDED OVER THE CONTENTS AND A TOP COVER OF 20 MIL SYNTHETIC LINER WAS SEWED IN PLACE. THREE FEET OF TOP SOIL WAS PLACED ON TOP OF THE LINED TRENCH AND COMPACTED. THE ORIGINAL PIT WAS BACKFILLED WITH CLEAN SOIL, COMPACTED, AND LEVELLED TO GRADE. CONFIRMATION SAMPLES WERE TAKEN FROM THE EXCAVATED PIT PRIOR TO BACKFILLING AND ARE ATTACHED. THE PIT CLOSURE WAS STARTED ON MAY 12, 2006 AND COMPLETED ON MAY 26, 2006.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines <input checked="" type="checkbox"/> , a general permit <input type="checkbox"/> , or an (attached) alternative OCD-approved plan <input type="checkbox"/> .	
Date: <u>6/1/06</u>	
Printed Name/Title <u>CLIFF BRUNSON, PRESIDENT, BBC INTL.</u>	Signature <u>Cliff P. Brunson</u> FOR CHESAPEAKE OPERATING, INC. _____
Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or	
Approval: _____	
Printed Name/Title <u>Environmental Engineer</u>	Signature <u>LW Johnson</u> Date: <u>6.2.06</u>



PHONE (505) 383-2326 • 101 E. MARLAND • HOBBS, NM 88240

**FAX TO: (505) 397-0397**


Analyzed By: HM

METHOD: Standard Methods	4500-Cl-B
--------------------------	-----------

**NOTE:** Analysis performed on a 1:4 w:v aqueous extract.

05-22-06  
Date

**PLEASE NOTE: Liability and Damages.** Cardinal and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



2111 Beachwood, Abilene, TX 79603 101 East Marland, Hobbs, NM 88240  
(915) 673-7001 Fax (915) 673-7020 (506) 393-2326 Fax (505) 393-2476

### CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

Page 1 of 1[illegible]

T Cardinal cannot accept verbal changes. Please fax written changes to 605-393-2476.