	· •
Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	May 27, 2004
District I 1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	<u>30-025-34948</u> 5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE FEE
District IV	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	o. State on & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: Grama Ridge East 34 State
1 Type of Well	8. Well Number
Oil Well Gas Well Image: Second seco	
2. Name of Operator Nearthurg Producing Company	9. OGRID Number
	015742 10. Pool name or Wildcat
3300 N A St., Bldg 2, Ste 120, Midland, TX 79705	Grama Ridge; Norman bine Sp NE
4. Well Location	
Unit LetterC: 1548feet from theNorth line and	990 feet from the East line
	01282930.37
Section 34 Township 21S Range 34E 11. Elevation (Show whether DR, RKB, RT, GR, etc.	NMPM <u>of County</u> Lea
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well Dis	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction	
12. Check Appropriate Box to Indicate Nature of Notice,	et al constant
	Report, or Other Data glgl bl
	SEQUENT_REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI	NG OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING IN MULTIPLE CASING TEST AND COMPLETION CEMENT JOB	
OTHER: OTHER: TA and ch	hart X
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 	
NPC TA'd the subject well on 6/2/06. Test was witnessed by Mr. Gonza	les, OCD rep.
See attached work performed and signed chart.	
This Assessment of Terrenovant I	
This Approval of Temporary Abandonment Expires	2 1
Abandonment LXpiles	f
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below- grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan	
SIGNATURE TITLE Production	m Analyst DATE 6/21/06
E-mail address:	sjordan@nearburg.com Telephone No. 432/686-8235
For State Use Only	-
APPROVED BY Hary Wi Wink TITLE	DATELLE 1 () 2006
Conditions of Approval, if any:	

TIGHT HOLE-PLEASE DO NOT RELEASE ANY INFORMATION ON THIS WELL

5

Grama Ridge East 34 State #1 1,548' FNL and 990' FEL, Section 34, T21S, R34E Morrow Lea County, New Mexico ** ALL COSTS ARE FIELD ESTIMATES **

05/30/06 Well Repair Purpose: TA Well.
 Road rig & crew to location from Osage Boyd 15 #5 in Dagger Draw. MIRU Mesa Well
 Service pulling unit. SDFN. Will POOH w/ tbg & TAC in the AM.
 Current Operation This AM: POH w/ tbg.

05/31/06 Well Repair Purpose: TA Well.

Well did not have any pressure on tbg or csg. ND WH & NU BOP. Release TAC. POOH w/ 275 jts- 2 3/8" L-80 4.7#EUE 8rd tbg, 2 3/8" x 7" TAC w/ 45K shear. LD TAC. LD 7 jts- 2 3/8" L-80 tbg on pipe racks w/ 2 3/8" API SSN and last jt 2 3/8" L-80 tbg (open ended as tail pipe). MIRU JSI electric line truck. RIH w/ 7" JB & 5.719" OD Gauge ring to 9098'. Did not have any obstructions. PU & RIH w/ 7" Alpha CIBP & set @ 9030' using casing collar log correlated to Schlumbergers log. RIH & dump bail 35' cmt on top of CIBP. TOC @ 8995'. RDMO JSI electric line truck. Close BOP blinds. SDFN. Will test CIBP in the AM before RIH w/ tbg to circulate pkr fluid. Current Operation This AM: Pressure test CIBP.

06/01/06 Well Repair Purpose: TA Well.
Open BOP blinds. Have Lucky reverse pump load csg w/ 60 Bbls 2% KCL wtr. Close BOP blinds. Pressure test csg to500# & hold for 10 minutes. Held good pressure. Blew dn to reverse pit. Open BOP blinds. PU & RIH w/ 275 jts- 2 3/8"N-80 4.7# EUE 8rd tbg (8940'). Tagged TOC @ 8945' w/ 5' in on 276th jt. RU Lucky reverse pump to reverse circulate360 Bbls 2% KCL wtr w/ double inhibited pkr fluid dn csg & out tbg to frac tank @ avg 2 bpm. Pressure test csg again after circulating pkr fluid & held 500#. POOH & LD 275 jts- 2 3/8" N-80 tbg on pipe racks. Have a total of 283 jts- 2 7/8"N-80 4.7# EUE 8rd tbg to move to Artesia yard in the AM. ND BOP & NU B1 bonnett w/ 2" valve. Trickle in 2% KCL wtr / pkr fluid dn csg til full. Close BOP blinds. SDFN. Will pressure test csg w/ chart recorder in the AM.

Current Operation This AM: Pressure test csg.

06/02/06 Well Repair Purpose: TA Well.

Had Lucky reverse pump top off csg w/ 2% KCL wtr & pkr fluid. Put chart recorder in line to record csg pressure. Pressure test csg to start pressure @ 630# for 32 minutes & finish pressure @ 625#. Made an acceptable chart. Had E.L. Gonzales w/ OCD on location to witness the test. Bled dn csg pressure. Removed chart from recorder. RDMO Mesa pulling unit & Lucky reverse pump. Will send chart in to Midland office to be filed w/ C-103 @ OCD office. Had Two-State load 283 jts- 2 3/8" L-80 4.7# EUE 8rd tbg from pipe racks & take to Artesia yard. Also had 3 more jts- 2 3/8"tbg on boards they also took along w/ (7) 1" T-66 rods. Release all equipment. FINAL REPORT.

