

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised June 10, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-20856
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator ConocoPhillips Company		6. State Oil & Gas Lease No. A-1334-1
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762		7. Lease Name or Unit Agreement Name VACUUM GLORIETA EAST UNIT TRACT 4
4. Well Location Unit Letter <u>ED</u> : 810 feet from the <u>NORTH</u> line and <u>660</u> feet from the <u>WEST</u> line Section <u>33</u> Township <u>17S</u> Range <u>35E</u> NMPM County <u>LEA</u>		8. Well Number 01
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3957" RKB, 3947" GL		9. OGRID Number 217817
		10. Pool name or Wildcat VACUUM GLORIETA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: DOWNHOLE FAILURE ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

REPAIR DOWNHOLE FAILURE:

SEE ATTACHED



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gay Thomas TITLE Regulatory Assistant DATE 07/11/2006

Gay.Thomas@conocophillips.com

Type or print name Gay Thomas

E-mail address:

Telephone No. (432)368-1217

(This space for State use)

APPROVED BY Gay W. Wink TITLE

DATE JUL 14 2006

Conditions of approval, if any:

OC FIELD REPRESENTATIVE II/STAFF MANAGER



Daily summary

VACUUM GLORIETA EAST UNIT 004-01

Job Type: REPAIR DOWNHOLE FAILURE

API / UWI 300252085600	Field Name DISTRICT - E. VACUUM SUB-D	Area BUCKEYE	County LEA	State/Province NEW MEXICO	Operator CONOCOPHILLIPS	License No.
Original KB Elevation (ft) 3,957.00	Ground Elevation (ft) 3,947.00	KB-CF (ft) 3,957.00	KB-TH (ft) 3,957.00	Spud Date 7/21/1964 7:00:00 PM	Rig Release Date 8/2/1964 11:00:00 PM	

Start Date	Last 24hr Sum	Day Total	Cum Cost
5/2/2006 08:30	MIRU Nabors DD unit. POOH w rods and found rods parted in box 106 rods from surface in the 7/8". Layed down all rods for replacement RU pump truck & ND wellhead, NU BOP pull tubing up to rod part POOH w plunger and standing valve then POOH w rest of tubing leaving 20 stands for kill string. SDFN		
5/3/2006 07:00	Finish POOH w tubing, lay down tubing pump. Pick up new 30' tubing pump and RIH w tubing while pressure testing layed down 1 joint that was crooked. RIH w pump plunger 1 1/4" sinker bars and 1 1/2" sinker bars, 3 new 7/8" guided rods. SDFN		
5/4/2006 07:00	Finish RIH with fiberglass rods (see attachments for design), space pump out, hang on PU, load and test tubing, check pump action RDMO.		