Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103	
Office District I	Energy, Minerals and Natural Resources		May 27, 2004 WELL API NO.: 30 025 01141	
1625 N. French Dr., Hobbs, NM 88240			WELL API	NO.: 30 025 01141
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5 Indicate	Type of Leace
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM				
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Na	me or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Nw Mexico AN- State	
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other			8. Well Nu	mber: 6
2. Name of Operator: CrownQuest Operating, LLC			9. OGRID Number: 213190	
3. Address of Operator: c/o P.O. Box 953, Midland, TX 79702			10. Pool name or Wildcat Saunders East Warren-Tubb Pool Perme Upper	
4. Well Location			<u> </u>	Territo dipperi
Unit Letter O : 64	60 feet from the 5 li	ine and 1976	feet from the	e E line
Section 22	Township 14S Range		NMPM	Lea County
	11. Elevation (Show whether DR): 3531°	The state of the s
Pit or Below-grade Tank Application or Closure				
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
12. Chook reproprieto Don to maiotto rittato, report or other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		X ALTERING CASING
 -	CHANGE PLANS	COMMENCE DRI		<u> </u>
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	I JOB	
OTHER:		OTHER: Well put		
	eted operations. (Clearly state all			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
or recompletion.				1213141516
or recompletion. 5-15-06: NU BOP & POH w/tubing. RIH w/2 3/8" tubing. Check for scale, corrosion & paraffin. 5-16-06: Pulled all tubing out of hole, ran in hole with new 2 7/8" tubing, seating nipple. 5-17-06: Tagged PBTD @ 9873'. Ran in hole with new pump & rods. Installed new wellhead. 5-18-06: Loaded hole with fresh water, tested to 420 psi – held. Set stroke for pumping unit. 5-19-06: Wellhead hooked up, made repairs to pumping unit. Well put back into production – well on compliance order to return to production.				
5-16-06: Pulled all tubing out of hole, ran in hole with new 2 7/8" tubing, seating nipple.				
5-17-06: Tagged PBTD @ 9873'. Ran in hole with new pump & rods. Installed new wellhead.				
5-18-06: Loaded hole with fresh water, tested to 420 psi – held. Set stroke for pumping unit.				
5-19-06: Wellhead hooked up, made repairs to pumping unit. Well put back into production – well on compliance order to return to production.				
Wen put onck into production – wen on compnance order to return to production.				
			1	So reti
				60 62 82 12 81 81.
I hereby certify that the information a	hoveds true and complete to the h	ect of my knowledge	a and baliaf	[About Long and Co. Al. of a grown of the state of the s
grade tank has been/will be constructed out	losed according to NMOCD guidelines ?	K, a general permit 🔲 o	or an (attached) :	alternative OCD-approved plan .
			, ,	
SIGNATURE ////	<u>leho</u> TITLE_	_Regulatory Agent_	********	DATE6-9-06
Type or print name Ann E. Ritc	hie E-mail address: ann.ritch	nie@wtor.net Toler	nhone No · 4	32 684-6381
For State Use Only		~	•	J ∠ 007 *0J01
		PETROLEUM EN	GHIERO	JUL 2 1 2006
APPROVED BY:	TITLE		- I OF FU	DATE
Conditions of Approval (if any):				•