

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
May 27, 2004

WELL API NO. 30-025-11506
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name LANGLIE JAL UNIT
8. Well Number WIW #72
9. OGRID Number 188483
10. Pool name or Wildcat LANGLIE MATTIX, 7 RVRSQ

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other WIW ☐
2. Name of Operator PHOENIX HYDROCARBONS OPERATING CORPORATION
3. Address of Operator P O BOX 3638, MIDLAND, TX 79702
4. Well Location Unit Letter <u>C</u> : <u>660</u> feet from the <u>NORTH</u> line and <u>2310</u> feet from the <u>WEST</u> line Section <u>8</u> Township <u>25S</u> Range <u>37E</u> NMPM LEA County <u>NM</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3190 GR


Pit or Below-grade Tank Application ☐ or Closure ☐
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☒	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER ☐	CASING/CEMENT JOB ☐
	OTHER FAILED WELL INTEGRITY TEST ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 6/16/06
1. RU Kill Truck
 2. Pressure back side to 620 psi. Dropped 120 psi in 15 minutes.
 3. Failed test.
 4. R. D. evaluate for remedial work.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE <u>Phyllis R. Gunter</u>	TITLE <u>AGENT</u>	DATE <u>7/24/06</u>
Type or print name <u>Phyllis R. Gunter</u>	E-mail address: <u>PHYGUN@AOL.COM</u>	Telephone No. <u>432-686-9800</u>
For State Use Only		JUL 26 2006
APPROVED BY: <u>Lang W. Wink</u>	TITLE <u>FIELD REPRESENTATIVE II/STAFF MANAGER</u>	DATE _____
Conditions of Approval (if any): _____		