

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-23866
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1506
7. Lease Name or Unit Agreement Name LANGLIE JAL UNIT
8. Well Number WIW #23
9. OGRID Number 188483
10. Pool name or Wildcat LANGLIE MATTIX, 7 RVRSQ

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other WIW

2. Name of Operator
PHOENIX HYDROCARBONS OPERATING CORPORATION

3. Address of Operator
P O BOX 3638, MIDLAND, TX 79702

4. Well Location
Unit Letter P : 660 feet from the EAST line and 660 feet from the SOUTH line
Section 32 Township 24S Range 37E NMPM LEA County NM

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3253' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:


REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6/14/06 - 6/15/06

1. MIRU. POOH w/tbg and packer. Packer came out without rubber.
2. TIH w/tbg & redressed packer. Packer sticking on bottom.
3. Set pkr and load backside.
4. Pressure test backside would not hold
5. RD Evaluate for further remedial action.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Phyllis R. Gunter TITLE AGENT DATE 7/24/06

Type or print name Phyllis R. Gunter E-mail address: PHYGUN@AOL.COM Telephone No. 432-680-0569

For State Use Only

APPROVED BY: Larry W. Wink

TITLE FIELD REPRESENTATIVE II/STAFF MANAGER

DATE JUL 26 2006

Conditions of Approval (if any):