

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
May 27, 2004

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-29219
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other DHC <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Marathon Oil Company		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 3487 Houston, TX 77253-3487		7. Lease Name or Unit Agreement Name: J.L. Muncy
4. Well Location Unit Letter <u>G</u> : <u>2086</u> feet from the <u>North</u> line and <u>1874</u> feet from the <u>East</u> line Section <u>24</u> Township <u>22-S</u> Range <u>37-E</u> NMPM County <u>Lea</u>		8. Well Number 7
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3318' GR		9. OGRID Number 14021
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		10. Pool name or Wildcat Tubb (60240) / Granite Wash (62730)

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: Downhole Commingle <input checked="" type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Marathon Oil Company has completed operations to downhole commingle the J.L. Muncy No. 7 in the Tubb & Granite Wash formations as permitted by Administrative Order No. DHC-3476.
07/12/2005 - 07/21/2005: Well work was done to clean out sand and remove the retrievable bridge plug that isolated the Granite Wash formation. The well was put on production from both pools on 07/21/2005. Please see new wellbore diagram for commingled well attached with this sundry. Also, See attached letter with details of reporting error for this well since the time of downhole commingling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Charles E. Kendrix TITLE Regulatory Compliance Rep DATE 07/13/2006

Type or print name Charles E. Kendrix

E-mail address: cekendrix@marathonoil.com

Telephone No. 713-296-2096

For State Use Only

APPROVED BY [Signature] TITLE PETROLEUM ENGINEER DATE JUL 31 2006

Conditions of Approval, if any:




J.L. Muncy No. 7 DHC
Tubb / Granite Wash

DHC - 3476


Elevation 3318'

Marathon Oil Company
J.L. Muncy No. 7
21-Jul-05

Surface Casing
9 5/8" 32# set @ 1220' cmtd w/ 700 sks



Tubb perfs 5814' to 6142'



Seating Nipple @ 7436'
Desander / gas separator

Bottom of Mud Jt @ 7544'

PBTB @ 7575'

Wantz Granite Wash perfs 7318' - 7560'

Production Casing
7" 23# & 26# K-55 & N-80 set @ 7591' Cmtd w/
2700 sks

Well Name & Number:	J.L. Muncy No. 7		Lease	J.L. Muncy		
County or Parish:	Lea	State/Prov.	New Mexico		Country:	USA
Perforations: (MD)	5814'-6142'		(TVD)	7591		
Date Completed:	08/13/04	GL:		3318'	RKB:	
Prepared By:	Charles Kendrix		Last Revision Date:		08/31/04	