Submit 3 Copies To Appropriate District Office	State of New Me	exico	Form C-103
District I	Energy, Minerals and Natu	ıral Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-025-21026
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION		5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		STATE FEE
District IV	Santa Fe, NM 8'	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			VA-0433
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS ON WELLS ISALS TO DRILL OR TO DEEPEN OR PL CATION FOR PERMIT" (FORM C-101) FOR	UG/BACK/TO A	7. Lease Name or Unit Agreement Name  Maljamar APB State
1 Type of Well Oil Well Gas Well Other Dept. 9. Well Number			
2. Name of Operator		- 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	1 19 OGRID Number 00 025575
Yates Petroleum Corporat	ion (8)	<b>3</b>	023373
3. Address of Operator 105 S. 4 <sup>th</sup> Street, Artesia,	NDA 99310		510. Pool name or Wildcat
	NM 88210	<u> </u>	Wildcat Mississippian (Gas)
4. Well Location Unit Letter P:	660 feet from the South	विक्रह्याते अ	660 feet from the East line
Section 34		nge 32E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4287' GR			
Pit or Below-grade Tank Application or Closure			
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Co	nstruction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN	ITENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS. P & A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	「JOB □
OTHER:		OTHER:	Re-Entry Operations
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
4.39.06 MIDIT multipe mult. TOOM who do not 4.12.			
<b>4-28-06</b> MIRU pulling unit. TOOH w/rods and tubing. <b>5-1-06</b> TIH w/tubing and scraper to 4128'. Pumped 225 bbls water down annulus.			
5-2-06 Set cement retainer @ 4100'. Squeezed 100 sx "C" Neat. Did not squeeze. Pumped 50 sx "C" Neat. Squeezed to 3100#.			
5-3-06 RD unit.			
<b>6-1-06</b> RUPU. Drilled cement and retainer. Drilled out CIBP @ 4455'. <b>6-25-06</b> RURT.			
7-8-06 Drilled out cement plugs and TD 7-7/8" hole to 12911'.			
7-11-06 TIH open-ended to 12900'. Pumped Plug #1 @ 12900' w/25 sx "H". Pumped Plug #2 @ 9309' w/35 sx "H". Pumped Plug #3			
@ 7766' w/35 sx "H". Pumped Plug #4 @ 5750' w/35 sx "H". Pumped Plug #5 @ 4553' w/50 sx "H". WOC and tagged @ 4403'.			
Pumped Plug #6 @ 1340' w/35 sx "H".  7-12-06 Pumped Plug #7 @ 710' w/50 sx "H". WOC. Tagged @ 550'. Pumped Plug #8 @ 60' to surface w/10 sx "H".			
7-12-00 1 uniped 1 lag #7 (@ 710 w/30 sx 11 . woe. 1 agged (@ 330 . Funiped Plug #8 (@ 60 to surface w/10 sx "H".			
WELL IS PLUGGED AND ABANDONED. FINAL REPORT.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed on closed according to NMOCD guidelines $\square$ , a general permit $\square$ or an (attached) alternative OCD-approved plan $\square$ .			
SIGNATURE TITLE Regulatory Compliance Technician DATE 7-18-06			
Type or print name Stormi Da For State Use Only	vis E-mail address:	stormid@ypcn	m.com Telephone No 505-748-1471
		artion	EUM ENGINEER
APPROVED BY: Conditions of Approval (if any):	TITLE_	PEINUL	DATE 3 1 2006