

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-34829

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Townsend State

8. Well Number
9

9. OGRID Number
6137

10. Pool name or Wildcat
Big Dog; Strawn, South

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
Devon Energy Production Company, LP

3. Address of Operator
20 North Broadway, Oklahoma City, OK 73102-8260 405-552-8198

4. Well Location
Unit Letter J : 3927 feet from the North line and 1940 feet from the East line
Section 2 Township 16S Range 35E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3990' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Completion Report ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6/21/06 - 8/8/06

MIRU. Attempted to release packer.. Cut tubing above packer. POOH. RIH w/ jars and overshot but unable to loosen. Set CIBP at 12,227'. Tested CIBP to 1000 # - held good. Dump bail 35' of cement on top of CIBP. TOC at 12,292'. RIH and perforate 11918-11928'; 3 SPF. POOH with gun. RIH with packer and set at 11,848'. Tested casing to 1000 psi - held good. RU & swab well. Acidized well with 28.5 bbls 7.5% HCl w/ 20% Methanol. RD. Swabbed well. Release packer and POH with tubing and packer. Frac w/ 24,011 gals 70 DSHQ Binary Foam w/ 20,000# Ultraprop 18/40 and flushed with 10,930 gals 61 DSHQ Binary Foam. RIH and circulate and clean hole. POOH. RIH with packer, on/off tool, and tubing. Set packer at 11,851' w/ 10,000# compression. Swabbed well - no fluid. Shut well in. Open well, bled down and loaded casing with 46 bbls 2% KCl and loaded tubing with 42 bbls 2% KCl. Release packer and POH with tubing and packer. Attempt to recomplate the Atoka was unsuccessful. Set CIBP at 11,900'. Dump bail 35' of cement on to of CIBP. Perforated Strawn at 11524-11530' and 11538-11542' at 3 SPF. RD. RIH with packer and set at 11475' w/ 10,000 # of compression. Swab well. Shut well in. Acidized Strawn with 1500 gallons 15% NEFE. RD. Swabbed well - no fluid. Shut well in and RD pulling Unit. Attempt to recomplate to the Strawn was unsuccessful.

Each attempt in the Atoka and Strawn was unsuccessful.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE [Signature] TITLE Sr. Staff Eng. Tech DATE 8/15/06

Type or print name Norvella Adams E-mail address: norvella.adams@dvn.com Telephone No. 405-552-8198

For State Use Only

APPROVED BY: [Signature] TITLE PETROLEUM ENGINEER DATE AUG 23 2006

Conditions of Approval (if any):

2A Shoe Bar Morrow North