UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**



FORM APPROVED OMB NO. 1004-0137 Expires March 31, 2007

5. Lease Serial No.

٨	IM	M	мг	16	21	ı

SUNDRY NUTICES	NMNM0631					
Do not use this form for particles abandoned well. Use Form	6. If Indian, Allottee or Tribe Name					
SUBMIT IN TRIPLICATE -	7. If Unit or CA/Agreement, Name and/or No.					
1. Type of Well Oil Well X Gas Well Other 2. Name of Operator Samson Resources Company		8. Well Name and No. Federal 11-20-34 No. 2 9. API Well No.				
3a. Address		3b. Phone No. (include are	ea code)	30-025-2193		
200 N. Loraine St., Ste 1010; Midla		(432) 683-7063	3	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey 2080' FWL & 760' FSL Sec. 11-20S-34			:	(Lea) Bone		
				Lea	NM	
12. CHECK APPROPRIATE	BOX(ES) TO INI	DICATE NATURE OF N	NOTICE, REPO	ORT, OR OTH	ER DATA	
TYPE OF SUBMISSION		TYP	PE OF ACTION		•	
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injecti	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production Reclamatio Recomplet X Temporaril Water Disp	e [Water Shut-Off Well Integrity Other	
Attach the Bond under which the work will be perfollowing completion of the involved operations. testing has been completed. Final Abandonment determined that the final site is ready for final inspect. MIRU PU ND Tree. NU BOP's. Start to movement downhole RU WL. RIH. 2 3/8" tubing start and the start are represented by the the start are	If the operation results Notices shall be filed or ction.) rlse off the overtuck at 5720'. e. Ran CBL from ish @ 5645' POOH & RD WL 7/8" collar on 20' bailer, dump op @ 8134'. UWH.	in a multiple completion or really after all requirements, incorrenshot. Rotated & Unable to move. In 10958' to 6200'. truck.	ecompletion in a relation in a	inew interval, a Foon, have been considered and down coff @ 5648'	rm 3160-4 shall be filed once upleted, and the operator has 5 to 8 pts, no , RD WL truck,	
14. I hereby certify that the foregoing is true and correct		Title			9107/	
Name (Printed/Typed) J. J. Farrell, III		District Engineer				
		Date 8/4/06				
- Alle			TIOE LIGE			
	IS SPACE FOR FE	DERAL OR STATE OF	FICE USE		***	
Conditions of approval, if any are attached. Approval certify that the applicant holds legal or equitable title twhich would entitle the applicant to conduct operations	o those rights in the su	warrant or bject lease Office	t, Eng	D	nte /28/2006	



Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 505-627-0272

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- 2. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi.

 The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, call 505-627-0272; Eddy County, 505-234-5972; Lea County 505-393-3612.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for a 12 month period provided that the operator:

45 114 145

সংক্রম কু ভাগ্রান্ত 💥

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- Attaches a clear copy or the original of the pressure test chart.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnessed by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Ref: IM: NM-95-022 (12/16/94)

acs -- 9/24/96