District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

For drilling and production facilities, submit to appropriate NMOCD District Office.

Form C-144

June 1, 2004

Oil Conservation Division 1220 South St. Francis Dr.

For downstream facilities, submit to Santa Fe Santa Fe, NM 87505

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes \(\subseteq \) No \(\subseteq \)

Type of action: Registration of a pit or below-grade tank \(\subseteq \) Closure of a pit or below-grade tank \(\subseteq \) Operator: CHESAPEAKE OPERATING. INC. Telephone: 432-687-2992 e-mail address: SSTRICKLIN@CHKENERGY.CO Address: P. O. BOX 11050 MIDLAND, TEXAS 79702-8050 Facility or well name: A M YORK WELL 003 County: LEA __ Longitude ______ NAD: 1927 [] 1983 [Latitude Surface Owner: Federal State Private Indian Below-grade tank Type: Drilling X Production Disposal D Volume: ____bbl Type of fluid: ____ Workover 🗌 Emergency 🔲 Construction material: Lined X Unlined Double-walled, with leak detection? Yes \(\sigma\) If not, explain why not. Liner type: Synthetic X Thickness 12 mil Clay Pit Volume 12,139 bbl Depth to ground water (vertical distance from bottom of pit to seasonal Less than 50 feet (20 points) high water elevation of ground water.) (10 points) 50 feet or more, but less than 100 feet 73'+ (0 points) 0 100 feet or more Wellhead protection area: (Less than 200 feet from a private domestic (20 points) (0 points) 0 water source, or less than 1000 feet from all other water sources.) No Distance to surface water: (horizontal distance to all wetlands, playas, Less than 200 feet (20 points) irrigation canals, ditches, and perennial and ephemeral watercourses.) 200 feet or more, but less than 1000 feet (10 points) 1000 feet or more (0 points) 0 Ranking Score (Total Points) 0 If this is a pit closure: (1) Attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if your are burying in place) onsite X offsite I If offsite, name of facility ____. (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No 🔯 Yes 🔲 If yes, show depth below ground surface ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavations. Additional Comments: A SIDE DEEP BURIAL TRENCH WAS EXCAVATED NEXT TO THE PIT. THE TRENCH WAS LINED WITH A 20 MIL SYNTETIC LINER, THE PIT CONTENTS WERE THEN PLACED INTO THE LINED TRENCH. THE SIDES OF THE TRENCH WERE FOLDED OVER THE CONTENTS AND A TOP COVER OF 20 MIL SYNTHETIC LINER WAS SEWED IN PLACE. THREE FEET OF TOP SOIL WAS PLACED ON TOP OF THE LINED TRENCH AND COMPACTED. THE ORIGINAL PIT WAS BACKFILLED WITH CLEAN SOIL, COMPACTED, AND LEVELLED TO GRADE. CONFIRMATION SAMPLES WERE TAKEN FROM THE EXCAVATED PIT PRIOR TO BACKFILLING AND ARE ATTACHED. THE PIT CLOSURE WAS STARTED ON SEPTEMBER 15, 2006 AND COMPLETED ON SEPTEMBER 27, 2006. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines 🗵, a general permit 🗌, or an (attached) alternative OCD-approved plan 🔲. Date: 10/9/06 CLIFF BRUNSON, PRESIDENT, BBC INTL. _ Signature _ Cliff P. Tuna FOR CHESAPEAKE OPERATING, INC.___ Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or Approval:

Printed Name/Title GARYW.WINK STAFF MOR Signature Lauy W. Wink Date: 10/10/06





PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR BBC INTERNATIONAL, INC. ATTN: CLIFF BRUNSON P.O. BOX 805 HOBBS, NM 88241 FAX TO: (505) 397-0397

Receiving Date: 09/25/06
Reporting Date: 09/25/06
Project Number: NOT GIVEN
Project Name: AM YORK WELL #3
Project Location: EUNICE, NM

Analysis Date: 09/25/06 Sampling Date: 09/23/06 Sample Type: SOIL

Sample Condition: COOL & INTACT

Sample Received By: NF

Analyzed By: HM

METHOD: Standard Methods 4500-Cl'B NOTE: Analysis performed on a 1:4 w:v aqueous extract.

Chemist S. M. semi

09-25-06

Date

H11568

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

ARDINAL LAS ORATORIES, INC.
2111 Seechwood, Abilene, TX 79603. 101 East Marland, Hobbs, NM 88240
(\$15) 673-7001 Fax (\$15) 673-7020 (505) 393-2325 Fax (505) 393-2475

Company Nama: BBC International, Int.									X (;	V-19-19-19-19-19-19-19-19-19-19-19-19-19-						Page_/_of_/											
Project Manager Cliff Bringson									- -	BILLTO						ANALYSIS REQUEST											
ARRISES: P.O. Box 801									-	P:O. #:							l	1	1	.							
								C	Company:									-						1			
								At	Attn:						l		'	1	į								
Phona # 397-6398 Fax # 397-0397								A	Address: 37						l	i			ļ			1					
Project #: Project Owner:								CI	City:									-	ł	1							
Project Name: Am York well # 3							St	State: 2 p;										1		1							
Project Location: Eurice, Non							PI	Phone #:					1				1	1	-								
Samplar Kama: Oscar France								_	Fax #:					1 4	1					1			1				
tour the research.	MAKIN MAKIN				ΙX	PRESERV SAMPLING						73]			1.	1					1					
			<u> </u>	4		<u>بر</u>					Ί		T.		1	Chlori	1		1			1			1	1	
1			i	(C)014P	133	4TE	EB			-	1					13	<u> </u>		ł		1	1,	1				
Lab I.D.	Sample	1,1	P¦		# CONTAINERS	GROUNDWATER	WASTEWATER	ā	<u> </u>		냃	占	ŀ	ļ		13	Ī		l	1		-					
	F			(G)RAB DR	iš	S	SIE	_ <u>"</u>		草	18	8	草			~	1						1		-		
1111212	0 : 2		1			5	ž	SOIL CRIDE OIL	17	5	12	造	6	DATE	TIME	<u> </u>		<u> </u>									
HIISUS-1	P.+ 80+1	64	٠	G	1	-		1	\perp	_		-	1_	9/23/06	9:00	V											
h		-	· · · · · · · · · · · · · · · · · · ·	 	<u> </u>		_	_	\perp	1	_	<u> </u>															
	····	- 	,	╁	_				4	_	_	<u> </u>							<u> </u>								
			ļ	 	L.		_				L	_									<u> </u>						
			! - 	<u> </u>				1				L												L			
	· ;	- !	<u> </u>								L																
								\perp		L	L																
		-		_			\perp	L													1						
			!																					•			
	\ 							7					\neg					******									
המושה שייש אי שבובה: המישה לא השיים מישה און	المناه ها الا الاستراعات بما ميون الله ليمان والدوري بالماليوروم	المامود أولون	donoana han oo 1900 Arrens taideal fix Al	क्ष्म है। इस्तुला है।	ned un	HING HING	e h	HEEDER MARKETER MARKE	d w lo	ri, the	that be imited to the amount paid by the stant for the						Terms and Constitutes latered and be therefore in a security more from										
the second secon	क्षा हा अर्थ कर १३ है। उन्होंने अर्थ कर १६ कर	2 10 20 CAL CAL	these taleston of Ca. Househow's served Apr	nou kry orwi, te	Sando: Date	beim Holni	SHOT S	prione,	0 seed	Dec 1	OF 1014	of pre	an inc	LETTER BY CHICK,)	e substitution,			•	•				, haiding			 • ·	
RECENTE LOSS AND BATTAIN CALL AND AND THAT HE PART INDIVIDUAL BY BARN LANGE WHAT A BATTAIN AND AND THAT HE PART AND						***************************************	\// / Pno					чπ:	Д Үв			Add'l		₹ :		··········							
Time:							_	Fax Roou REMARKS																			
Reingrisona By Receive Chew Stem Stem								ير	1,11,11,11,11																		
19/25/06 (600) 17 19 19 19						1	10					·															
Day Sull Time: 70 tak tu							X	Illa I															•	ł			
Dolla Tollate Ontil								90 1																	- 1		
Sampler - UP) Bus - Otner: Cool Intact								(initials)								-]			
□ HO □ HO									At.						• .												

T Cardinal cannot accept yerbal changes. Please fax written changes to 505-393-2476.