

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-20174
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Cato San Andres
8. Well Number 84
9. OGRID Number 183718
10. Pool name or Wildcat Cato San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
UHC New Mexico Corp.

3. Address of Operator
P.O. Box 450, 303 W. Main, Ste. 300, Artesia, N.M. 88210

4. Well Location

Unit Letter H : 1980 feet from the north line and 660 feet from the east line

Section 14 Township 8S Range 30E NMPM Chavez County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

06-28-06 MIRU. Latch onto sand line, came apart. RIH w/ spear & 13 jts. Shut dn.

06-29-06 Loaded csg, drop cable cutters. Got sand line out of hole. Put on BOP, RIH w/ fishing tool. Unable to fish out cable cutters. Shut dn.

06-30-06 RIH w/ overshot & tbg, tag. Wash down to tag fish @ 3433'. Unable to fish out, POOH. Shut down.

07-05-06 RIH w/ overshot & tbg, tag. Wash down to fish, unable to latch on. POOH, clean off tools, RIH, tag, wash down. Fished out cable cutting & pulled out two stands. Shut down.

07-06-06 POOH w/ tbg, tried three more trips, unable to latch onto fish. RIH w/ packer to 2800', set packer. Test csg @ 300psi, held Ok. Bleed off well, POOH w/ tbg, shut dn.

07-07-06 RIH w/ mill shoe, collars & tbg to 3433', tag, started milling out to 3490'. Pulled out some cable & cable cutting, shut dn.

07-10-06 RIH w/ 2 jts, tag, p/u power swivel. Started milling out from 3490' to 3492'. POOH, changed mill shoe, RIH, tag. Shut dn.

07-11-06 Started drilling, couldn't pass through. POOH, changed shoe, RIH, tag @ 3492', couldn't pass through. RIH w/ overshot. Tool complications hindered any more drilling. Shut down.

07-12-06 POOH w/ tbg. Replaced shoe, RIH, tag @ 3496'. Ran another shoe, tag @ 3496'. Started wash down to TD @ 3655'. Circulate, clean, POOH w/ 3 stands. Shut down.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan.

SIGNATURE _____

TITLE Production Tech

DATE 8/2/06

Type or print name
For State Use Only

Ronnie Grado

E-mail address:

Telephone No. 505-746-4448

APPROVED BY:

Accepted for record - NMOCD

TITLE

DATE

10/5/06

Conditions of Approval (if any):