District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 For drilling and production facilities, submit to appropriate NMOCD District Office. For downstream facilities, submit to Santa Fe office

Form C-144

June 1, 2004

Pit or Below-Grade Tank Registration or Closure Is pit or below-grade tank covered by a "general plan"? Yes D No X Type of action: Registration of a pit or below-grade tank D Closure of a pit or below-grade tank X														
Operator: CHESAPEAKE OPERATING. INC. Telephone: 432-687-2992 e-mail address: SSTRICKLIN@CHKENERGY.C														
		U/L or Qtr/Qtr N	Sec 16	T 22S	_R 37E									
County: LEA Latitud														
Surface Owner: Federal 🗋 State 🛛 Private 🗋 Indian 🗌		0		_										
<u>Pit</u>	Below-grade tank	Below-grade tank												
Type: Drilling 🛛 Production 🗌 Disposal 🗍	Volume:bbl 7	Type of fluid:												
Workover 🔲 Emergency 🛄	Construction material	Construction material:												
Lined 🛛 Unlined 🗌	Double-walled, with l	Double-walled, with leak detection? Yes 🔲 If not, explain why not.												
Liner type: Synthetic 🛛 Thickness 12 mil Clay 🗌														
Pit Volume 12,139 bbl														
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.) 70'+	Less than 50 feet 50 feet or more, but le 100 feet or more	ss than 100 feet	(20 points) (10 points) (0 points) 0	5 6 5	3 (
Wellhead protection area: (Less than 200 feet from a private domestic	Yes		(20 points)											
water source, or less than 1000 feet from all other water sources.)	No		(0 points) 0	(0 points) 0										
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet	200 feet or more, but less than 1000 feet (10 points)												
	Ranking Score (Tota	l Points) .	- 10											
If this is a pit closure: (1) Attach a diagram of the facility showing the p	pit's relationship to other eq	uipment and tanks. (2) Indic	cate disposal locatio	on: (check the	onsite box if									
your are burying in place) onsite 🔀 offsite 🔲 If offsite, name of facilit	у	(3) Attach a general	description of reme	dial action tak	en including									

remediation start date and end date. (4) Groundwater encountered: No 🛛 Yes 🗌 If yes, show depth below ground surface ft. and attach sample results.

(5) Attach soil sample results and a diagram of sample locations and excavations.

Additional Comments:

A SIDE DEEP BURIAL TRENCH WAS EXCAVATED NEXT TO THE PIT. THE TRENCH WAS LINED WITH A 20 MIL SYNTETIC LINER. THE PIT CONTENTS WERE THEN PLACED INTO THE LINED TRENCH. THE SIDES OF THE TRENCH WERE FOLDED OVER THE CONTENTS AND A TOP COVER OF 20 MIL SYNTHETIC LINER WAS SEWED IN PLACE. THREE FEET OF TOP SOIL WAS PLACED ON TOP OF THE LINED TRENCH AND COMPACTED. THE ORIGINAL PIT WAS BACKFILLED WITH CLEAN SOIL, COMPACTED, AND LEVELLED TO GRADE. CONFIRMATION SAMPLES WERE TAKEN FROM THE EXCAVATED PIT PRIOR TO BACKFILLING AND ARE ATTACHED. THE PIT CLOSURE WAS STARTED ON OCTOBER 30, 2006 AND COMPLETED ON NOVEMBER 9, 2006.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit , or an (attached) alternative OCD-approved plan .

Date: <u>11/18/06</u> CLIFF BRUNSON, PRESIDENT, BBC INTL. Printed Name/Title FOR CHESAPEAKE OPERATING, INC
Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or
Approval: Printed Name/Title GARY W. WINK STAFF MGRignature Hary W. Wink Date: 11/20/06
0



PHONE (325) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR BBC INTERNATIONAL, INC. ATTN: CLIFF BRUNSON P.O. BOX 805 HOBBS, NM 88241 FAX TO: (505) 397-0397

Receiving Date: 11/10/06 Reporting Date: 11/11/06 Project Number: NOT GIVEN Project Name: RE COLE WELL #4 Project Location: EUNICE, NM Analysis Date: 11/11/06 Sampling Date: 11/10/06 Sample Type: SOIL Sample Condition: COOL & INTACT Sample Received By: NF Analyzed By: HM

LAB NO. SAMPLE ID	CI [—] (mg/Kg)
H11789-1 PIT BOTTOM	< 16
	·····
n	
Quality Control	480
True Value QC	500
% Recovery	98
Relative Percent Difference	6.0

METHOD: Standard Methods4500-CIBNOTE: Analysis performed on a 1:4 w:v aqueous extract.

ml. Yeno

jl-11-00 Date

H11789

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profils incurred by client, its subsidiaries, atilitates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. ARDINAL LABORATORIES, INC. 2111 Beechwood, Abilene, TX 79603 101 East Marland, Hobbs, NM 88240

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

:

(915) 673-7001 Fax (915) 673-7020 (505) 393-2326 Fax (505) 393-2476

Page / of (

Company Name: BBC International Inc.				BILL TO						ANALYSIS REQUEST																
Project Manager: Cliff Brunson							P.O. #:							[·		T				1	1	1	T	T		
Company Name: BRC International Inc. Project Manager: Cliff Brunson Address: P.O. Box 805						Company:]	ļ						ŧ							
City: Hoble State: Non Zip: 88211						Attn: Same/									1					1						
Phone # 397-6318 Fax # 397-0397						Address:														1	1					
Project #. Project Owner:							City:																			
Project Name: RECola Well 14						State: Zlp:]														
Project Location	EVNICE, NM							Phone #:																		
Sampler Name:	Cliff BRUNSON		_			_		Fax #:							ļ				1							
FOR LAB USE CILY					MA	TRUX	<u>(</u>	PRESERV SAMPLING						12										1		
Lab I.D.	Sample I.D.	(G)RAB OR (C)OMP.	# CONTAINERS	GROUNDWATER WASTEWATER	SOIL	CRUDE OIL	SLUDGE	OTHER :	ACID/BASE:	ICE / COOL	VIIILA.	DATE	TIME	Ch lor.												
H11787-1	lif Bottom	G	1		レ	Ĺ				4		11/10/06	12:30	~								<u> </u>			ļ	
		-									_											ļ			<u> </u>	
		_									4							_				 	 		<u> </u>	
											+							-+-							┟	
			$\left - \right $								╉														<u> </u>	<u>├</u>
		+			+						╉												<u> </u>	<u> </u>		
		+			+						+								-+				<u></u> :			
		-	$\left - \right $					-			╉						-+	+	-+				<u> </u>			
PLEASE NOTE: Locity and Durnayoe, Carden's Sublity and eleven's sublive remedy for any dam abing whether based in contrast or text, whether based in contrast or text, whether based in contrast or text, whether based in text or text, whether based in contrast or text, whether based in text or text, whether based in contrast or text, whether based in text or text, whether based in contrast or text, whether based in text or text																										
Sampler Rellnqu		Re	Celv	ed By	;	,				,			Phone Re							hone ax #:	* :					
(Qap Burn 2:10 m Jennifer						L	Cilkey Fax ROBUL							83	<u>.</u> .		<u>loir</u>	<u>ax #;</u>								
Reilinguished By: Dennifer Gilkey 7.40 2.40						' u l	Į.	l	2		-															
Delivered By: Sampler - UPS -	(Circle Qne)			Co	nple ol]Yes] No	Inta	ct				HI HI	ID BY: IIS)							•							

† Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476.