

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 3002509214
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. 34227
7. Lease Name or Unit Agreement Name Seven Rivers Queen Unit
8. Well Number 43
9. OGRID Number 220420
10. Pool name or Wildcat Seven Rivers Queen

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other - Injection

2. Name of Operator

Arena Resources Inc.

3. Address of Operator

4920 S. Lewis, Suite 107, Tulsa, OK 74105

4. Well Location

Unit Letter C : 660 feet from the North line and 1980 feet from the West line
Section 2 Township 23S Range 36E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3491' RKB

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: Casing ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

11-8-06 Dumped 30' of cement on plug with wireline.


11-10-06 Pressure tested casing, would not hold.

11-13-06 Change out ring gasket and bolts in well head.

11-14-06 Pressure tested casing, would not hold.

Proposal:

GIH with packer and RBP and search for casing leak. If leak is found, will repair.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Dg m Palmer

TITLE Production Supervisor

DATE 11-16-06

Type or print name Danny M. Palmer

E-mail address:

Telephone No. (505) 738-1739

For State Use Only

APPROVED BY: Mary W. Wink

TITLE

DATE NOV 28 2006

Conditions of Approval (if any)

OC FIELD REPRESENTATIVE II/STAFF MANAGER