


Deviation survey taken on MILLER-DYER'S GLADY'S # 1 well in
Lea County, New Mexico:


J - 33 - 125 - 38e
1980's & 1980E
30 - 025 - 36186

Depth	Deviation
475	0.50
989	0.25
1478	0.50
1975	1.00
2482	1.25
2940	0.25
3440	1.75
3722	0.75
4233	0.50
4560	1.00
4841	0.75
5342	1.00
5842	0.75
6320	0.75
6819	1.00
7070	1.25
7610	1.00
8109	0.75
8629	1.00
9121	0.75
9800	1.25

Before me, the undersigned authority, on this day personally appeared Henry McElroy, known to me to be the person whose name is subscribed hereto, who, after being duly sworn, on oath states that he is the drilling contractor of the well identified in this instrument and that such well was not intentionally deviated from the vertical whatsoever.



SWORN AND SUBSCRIBED TO before me this 30th day of April, 2001.



Clara Savage

Kz