

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-144  
June 1, 2004

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

For drilling and production facilities, submit to  
appropriate NMOCD District Office.  
For downstream facilities, submit to Santa Fe  
office

**Pit or Below-Grade Tank Registration or Closure**

Is pit or below-grade tank covered by a "general plan"? Yes ☐ No ☒

Type of action: Registration of a pit or below-grade tank ☐ Closure of a pit or below-grade tank ☒

Operator: <u>CHESAPEAKE OPERATING, INC.</u> Telephone: <u>432-687-2992</u> e-mail address: <u>SSTRICKLIN@CHKENERGY.COM</u>		
Address: <u>P. O. BOX 11050 MIDLAND, TEXAS 79702-8050</u>		
Facility or well name: <u>JORDAN 12 STATE WELL #4</u> API #: <u>30-025-37766</u> U/L or Qtr/Qtr <u>L</u> Sec <u>12</u> T <u>10S</u> R <u>32E</u>		
County: <u>LEA</u> Latitude _____ Longitude _____ NAD: 1927 <input type="checkbox"/> 1983 <input type="checkbox"/>		
Surface Owner: Federal <input type="checkbox"/> State <input type="checkbox"/> Private <input checked="" type="checkbox"/> Indian <input type="checkbox"/>		
<b>Pit</b> Type: Drilling <input checked="" type="checkbox"/> Production <input type="checkbox"/> Disposal <input type="checkbox"/> Workover <input type="checkbox"/> Emergency <input type="checkbox"/> Lined <input checked="" type="checkbox"/> Unlined <input type="checkbox"/> Liner type: Synthetic <input checked="" type="checkbox"/> Thickness <u>12</u> mil Clay <input type="checkbox"/> Pit Volume <u>12,139</u> bbl	<b>Below-grade tank</b> Volume: _____ bbl Type of fluid: _____ Construction material: _____ Double-walled, with leak detection? Yes <input type="checkbox"/> If not, explain why not. _____	
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.) <u>-50'</u>	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) 20 (10 points) ( 0 points)
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) ( 0 points) 0
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) ( 0 points) 0
<b>Ranking Score (Total Points)</b>		<b>20</b>

**If this is a pit closure:** (1) Attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if you are burying in place) onsite ☐ offsite ☒ If offsite, name of facility GANDY-MARLEY. (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No ☒ Yes ☐ If yes, show depth below ground surface \_\_\_\_\_ ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavations.

Additional Comments:
PIT CONTENTS WERE EXCAVATED AND TRANSPORTED TO THE GANDY-MARLEY, INC. NMOCD-APPROVED DISPOSAL FACILITY NEAR CAPROCK, NM. THE PIT WAS THEN BACKFILLED WITH CLEAN SOIL, COMPACTED, AND LEVELLED TO GRADE. THE PIT CLOSURE WAS STARTED ON NOVEMBER 21, 2006 AND COMPLETED ON DECEMBER 5, 2006. CONFIRMATION SAMPLES WERE TAKEN FROM THE EXCAVATED PIT PRIOR TO BACKFILLING AND ARE ATTACHED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐, or an (attached) alternative OCD-approved plan ☐.

Date: 12/9/06

CLIFF BRUNSON, PRESIDENT, BBC INTL.

Printed Name/Title

Signature

Cliff P. Brunson

FOR CHESAPEAKE OPERATING, INC.

Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or

Approval:

Printed Name/Title

GARY W. WINK, STAFF MGR

Signature

Gary W. Wink

Date:

12/12/06



PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

Receiving Date: 12/04/06  
Reporting Date: 12/05/06  
Project Number: #4  
Project Name: JORDAN  
Project Location: TATUM, NM

Analysis Date: 12/05/06  
Sampling Date: 12/04/06  
Sample Type: SOIL  
Sample Condition: COOL & INTACT  
Sample Received By: HM  
Analyzed By: HM

LAB NO.	SAMPLE ID	C <sup>-</sup> (mg/Kg)
H11865-1	JORDAN	64
Quality Control		470
True Value QC		500
% Recovery		94
Relative Percent Difference		8.2

METHOD: Standard Methods	4500-CIB
--------------------------	----------

NOTE: Analysis performed on a 1:4 w:v aqueous extract.

*Joseph S. Marino*  
Chemist

12-05-06  
Date

H11865

PLEASE NOTE: **Liability and Damages** Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



## CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

Page \_\_\_\_\_ of \_\_\_\_\_

[illegible]

† Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476.