


Deviation survey taken on Energen Resources
EDDY county New Mexico

W.L.S.U. # 8 R
30-025-32291

L-34/15S/35E
1950 FSL & 660 FWL
BHL 1870 FSL & 859 FWL

Depth	Deviation
4676	1.50
4770	3.00
4802	4.25
4864	4.00
4927	4.00
4970	3.00
5071	3.00
5165	3.00
5196	2.00
5228	1.00
5291	3.00
5353	4.00
5416	4.50
5511	5.00
5605	5.40
5706	5.10
5762	4.50
5825	4.50
6046	3.80
6109	3.30
6140	3.30
6203	3.50
6266	3.50
6358	3.30
6421	3.30
6484	3.30
6547	3.00
6705	2.80
6768	3.70
6799	3.80
6779	4.00
6901	3.75
7182	2.50
7192	2.50
7376	2.25
7688	1.75
8018	1.75
8511	2.25
8994	2.00
9485	1.75
9958	1.75
10074	0.75
10580	0.75
11057	0.75
11371	0.75



Before me, the undersigned authority, on this day personally appeared G. M. HALL, known to me to be the person whose name is subscribed hereto, who, after being duly sworn, on oath states that he is the drilling contractor of the well identified in this instrument and that such well was not intentionally deviated from the vertical whatsoever.

G. M. Hall

SWORN AND SUBSCRIBED TO before me t this the

day of

2005

Brenda Bill

