

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM

87505

State of New Mexico
Energy, Minerals and Natural ResourcesOIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

May 27, 2004

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <u>30-025-3877</u>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Apache Corporation		6. State Oil & Gas Lease No. N/A
3. Address of Operator 6120 S Yale Ave, Suite 1500 Tulsa, OK 74136-4224		7. Lease Name or Unit Agreement Name W.B. Maveety
4. Well Location Unit Letter <u>B</u> : <u>520</u> feet from the <u>North</u> line and <u>2,310</u> feet from the <u>East</u> line Section <u>35</u> Township <u>19S</u> Range <u>36E</u> NMPM County <u>Lea</u>		8. Well Number <u>11</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>3,647'</u>		9. OGRID Number <u>00873</u>
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>		10. Pool name or Wildcat Monument; Abo
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

 PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

 REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ P AND A ☐
 CASING/CEMENT JOB ☐
OTHER: Unsuccessful Attempt to Return Well to Production ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7/25/06 - 7/27/2006 MIRUSU. Isolated and prepared to squeeze casing leak.

7/28/2006 Squeezed casing leak fr/5520 - 5595 with 200 sx cmt.

7/31/06 - 8/1/06 Drilled out cmt and retainer.

8/2/06 Drilled out cmt and CIBP @ 7075'. Cleaned out hole to PBTD @ 7518'.

8/3/06 Perfed upper Abo @ 6948-52, 56-60, 64-68, 78-85, 6988-7020, 7036-38, 70-74 w/2 JSPF.

8/4/06 Acidized new Abo perfs fr/6948-7074 and old Abo perfs fr/7138-7372 with 7700 gals 15% HCl.

8/5/06 Swabbed well and recovered 198 bbls w/zero% oil cut.

8/7/06 Casing would not test. Squeezed casing leak fr/5520 - 5595 with 25 sx cmt. Casing tested okay.

8/8/06 - 8/10/06 Drilled out cmt. Circulated hole clean. Casing tested okay.

8/11/06 - 11/19/06 Tested Abo and found well to be noncommercial.


 I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

 SIGNATURE Sophie Mackay TITLE Engineering Tech DATE 01/15/2007
 Type or print name Sophie Mackay E-mail address: sophie.mackay@apachecorp.com Telephone No. (918)491-4864
For State Use Only
 APPROVED BY: Gary W. Wink OC FIELD REPRESENTATIVE II/STAFF MANAGER
 Conditions of Approval (if any): _____ DATE JAN 29 2007