District I 1625 N. French Dr., Hobbs, NM 88240 District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., House, Artesia, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-144 June 1, 2004

For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

Pit or Below-Grade Tank Registration or Closure	_
Is pit or below-grade tank covered by a "general plan"? Yes No	_
Type of action: Registration of a pit or below-grade tank Closure of a pit or below-grade tank	6

Address: 1-1 C 60 Box 66 8820 Facility or well name: MCA Unit # 393 API #:	one: <u>505-390-3429</u> e-mail address: <u>[</u> 60-9669 3002537879 U/L or Qtr/Qtr	<u>H</u> Sec <u>29</u> t <u>175</u> R <u>32<i>E</i></u>
County: Lea Latitude		NAD: 1927 🗌 1983 🗍
Surface Owner: Federal X State Private Indian		
Pit	Below-grade tank	
Type: Drilling X Production Disposal	Volume:bbl Type of fluid:	
Workover	Construction material:	
Lined X Unlined	Double-walled, with leak detection? Yes [] If not, explain why not.	
Liner type: Synthetic Thickness 12 mil Clay		
Pit Volume 3000 bbl		
	Less than 50 feet	(20 points)
Depth to ground water (vertical distance from bottom of pit to seasonal	50 feet or more, but less than 100 feet	(10 points)
high water elevation of ground water.)	100 feet or more	( 0 points)
	Yes	(20 points)
Wellhead protection area: (Less than 200 feet from a private domestic	No	( 0 points)
water source, or less than 1000 feet from all other water sources.)		0
Distance to surface water: (horizontal distance to all wetlands, playas,	Less than 200 feet	(20 points)
irrigation canals, ditches, and perennial and ephemeral watercourses.)	200 feet or more, but less than 1000 feet	(10 points)
irrigation canais, tricinos, and percimias and opposition	1000 feet or more	( 0 points)
this is a pit closure: (1) Attach a diagram of the facility showing the pions are burying in place) onsite 4 offsite 1 If offsite, name of facility.	Ranking Score (Total Points)  it's relationship to other equipment and tanks. (2) In (3) Attach a gene	ndicate disposal location: (check the onsite box if
Ethis is a pit closure: (1) Attach a diagram of the facility showing the property of the facility showing the property of the facility showing the property of the facility showing the property of the facility of the facili	it's relationship to other equipment and tanks. (2) In  (3) Attach a gene  Yes I If yes, show depth below ground surface vations.	ral description of remedial action taken including  ft. and attach sample results.
our are burying in place) onsite offsite offsite, name of facility, mediation start date and end date. (4) Groundwater encountered: No offsite offsite, name of facility, and a diagram of sample locations and excave Additional Comments:	it's relationship to other equipment and tanks. (2) In  (3) Attach a gene  Yes I If yes, show depth below ground surface vations.	ral description of remedial action taken including ft. and attach sample results.
our are burying in place) onsite offsite offsite, name of facility, mediation start date and end date. (4) Groundwater encountered: No offsite offsite, name of facility, and a diagram of sample locations and excave Additional Comments:	it's relationship to other equipment and tanks. (2) In  (3) Attach a gene  Yes I If yes, show depth below ground surface vations.	ral description of remedial action taken including ft. and attach sample results.
our are burying in place) onsite offsite offsite, name of facility, mediation start date and end date. (4) Groundwater encountered: No Attach soil sample results and a diagram of sample locations and excavandaditional Comments:	tr's relationship to other equipment and tanks. (2) In  (3) Attach a gene  Yes If yes, show depth below ground surface_ vations.	ral description of remedial action taken including ft. and attach sample results.  THE B 3 /4  2728293032  THE B 3 /4  THE B 3
our are burying in place) onsite offsite offsite, name of facility, mediation start date and end date. (4) Groundwater encountered: No Attach soil sample results and a diagram of sample locations and excavandaditional Comments:	tr's relationship to other equipment and tanks. (2) In  (3) Attach a gene  Yes If yes, show depth below ground surface_ vations.	ral description of remedial action taken including ft. and attach sample results.  THE B 3 /4  2728293032  THE B 3 /4  THE B 3
our are burying in place) onsite offsite offsite, name of facility, mediation start date and end date. (4) Groundwater encountered: No offsite offsite, name of facility, mediation start date and end date. (4) Groundwater encountered: No offsite offsite, name of facility, mediation start date and end date. (4) Groundwater encountered: No offsite offsite, name of facility, mediation start date and end date. (4) Groundwater encountered: No offsite offsite, name of facility, mediation start date and end date. (4) Groundwater encountered: No offsite offsite, name of facility, mediation start date and end date. (4) Groundwater encountered: No offsite offsite, name of facility, mediation start date and end date. (4) Groundwater encountered: No offsite off	it's relationship to other equipment and tanks. (2) In  (3) Attach a gene  Yes  If yes, show depth below ground surface  vations.  St of my knowledge and belief. I further certify the nes  A general permit  , or an (attached) alter	ral description of remedial action taken including ft. and attach sample results.  THE B 3 /4  2728293032  THE B 3 /4  THE B 3