Submit 3 Copies To Appropriate District Office <u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Energy, Minerals OIL CONSER 1220 Sout Santa F	VATION h St. Fra e, NM 8	ural Resources I DIVISION ncis Dr. 7505	6. State O B-1845	e Type (ATE [] vil & Ga	S Lease No.), 2003
SUNDRY NOTI (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC		EPEN OR PL	UG BACK TO A	7. Lease 1 Vacuum A	Name or Abo Uni	Unit Agreement Na t Btry 3 Tr 10	ame
PROPOSALS.)	CATION FOR FERMIT (FOR	um C-101) F	OK SUCH	0 11/ 11/2	1		
1. Type of Well:				8. Well N	umber	6	
Oil Well 🕅 Gas Well 🗌	Other					0	
2. Name of Operator				9. OGRID Number			
ConocoPhillips Company				217817			
3. Address of Operator 3300 N. Midland,	'A" St., Bldg. 6 #200D TX 79710			10. Pool name or Wildcat Vacuum; Abo Reef			
4. Well Location							
Unit Letter_L:	1650 feet from the	South	line and	330	_feet fro	m the West	line
Section 34	Township 17	'S R	ange 35E	NMPM		County Lea	
	11. Elevation (Show w 3933' GR	hether DR	R, RKB, RT, GR, et	tc.)			
12. Check A	Appropriate Box to In	ndicate N	lature of Notice	, Report or	Other	Data	
NOTICE OF IN				SEQUEN			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	1	REMEDIAL WOR			ALTERING CASING	G 🗌
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	ILLING OPNS	S. 🗌	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST A CEMENT JOB	ND			
OTHER:			OTHER: Log, Ch	g pump, retu	rn to pro	oduction	X

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/27/06 - 1/8/07: Run logs, change pump, and return well to production per the attached daily summary of work.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juck Laguelo	TITLE Agent	DATE 02/06/2007
	Judy.A.Bagw	ell@conocophillips.com
Type or print name Judy Bagwell	E-mail address:	Telephone No. (432)688-6924
(This space for State use) APPPROVED BY <u>Harry</u> W.W.W.k Conditions of approval, if any:	OC FIELD REPRESENTATIVE II/ 	STAFF MANAGER

				/ Summary				
PI/UWI 300250301200	County LEA	State/Province NEW MEXICO		e Legal Location 34, Twp. 17S, Rge. 35E	N/S Dist (ft) 1,650.00	N/S Ref FSL	E/W Dist (ft) 330.00	E/W Ref FWL
Fround Elevation (ft)	Original Spud D	Pate Rig Relea	ase Date	Latitude (DMS)	1,000.00	Longitude (DMS		
3,933.00	7/1/19	961 8	3/6/1961					
eport Start Date	Last 24hr Summary			· · · · · · · · · · · · · · · · · · ·				
12/27/2006				eting, participate in Go prog t plumbing to Well Head. SIC		RUPU. RU p	oump truck, bi	leed off 80
Гime Log	p3i, pump 120 bi	n to# down cog.	Disconneo		<u></u>			
Dur (hrs)				Operation				
	out tag out. Hold Tai p pulling unit & pump ell		ung		N.S.,	a désara		
1.00 disco teport Start Date	Innect well head plun Last 24hr Summary	nbing						
12/28/2006	Drive to location, 10#. NDWH. Cut		BOP. RU sp	n Tailgate Safety Meeting, ob pooler. TOH w/ 6 stands 2 7/ . SION				
Time Log				Operation				
1.00 safet	y meeting, tailgate sa		program					
2.00 kill w 0.50 tripp	ell, NDWH?NUBOP				1.1			etta sut
	on wire line/				1.12			Por con
4.00 trippi	ng tbg							
eport Start Date 12/29/2006	bbl 10# then tricl	kle down csg. TO	H w/ 2 7/8"	Tailgate Safety Meeting, & of the state of the safety Meeting, & of the safety (257 jts total), LDESP. I				
	0002 J. COR, KL	Baller. TH W/2	54 jts 2 7/8'	tbg. SIFWE				
Dur (hrs)		Baller. (TH W/ 2	54 jts 2 7/8'					
Dur (hrs) 0.50 safet 1.00 trip o	y meeting ut of hole with tubing		54 jts 2 7/8'	" tbg. SIFWE				
Dur (hrs) 0.50 safet 1.00 trip o 3.00 lay do 1.00 rig up 4.00 trip in	y meeting ut of hole with tubing own esp/rig down sp bailer, tag fill, rig do hole with tubing	ooler	54 jts 2 7/8'	" tbg. SIFWE		20 2 1		
Dur (hrs) 0.50 safet 1.00 trip o 3.00 lay do 1.00 rig up 4.00 trip in	y meeting ut of hole with tubing baller, tag fill, rig do hole with tubing Last 24hr Summary RU Hydrotest tul Schlumberger w Spectoscopy Co	ooler wn bailer bing scanners and ireline. Schlumbe mbo log form 883	d scan tubin erger Run 35' (top of fi	" tbg. SIFWE	NL compensate	ed neutron / I	NGS-C Natur	al GR
Dur (hrs) 0.50 safet 1.00 trip o 3.00 lay de 1.00 rig up 4.00 trip in eport Start Date 1/2/2007	y meeting ut of hole with tubing baller, tag fill, rig do hole with tubing Last 24hr Summary RU Hydrotest tul Schlumberger w Spectoscopy Co	ooler wn bailer bing scanners and ireline. Schlumbe mbo log form 883	d scan tubin erger Run 35' (top of fi	* tbg. SIFWE Operation Ing OOH. Found 123 YB, 13 #1. Casing collar locator/ Ci ill) to 7000°. Run #2 Scient	NL compensate	ed neutron / I	NGS-C Natur	al GR
Dur (hrs) 0.50 safet 1.00 trip o 3.00 lay de 1.00 rig up 4.00 trip in teport Start Date 1/2/2007	y meeting ut of hole with tubing own esp/rig down spi bailer, tag fill, rig do hole with tubing Last 24hr Summary RU Hydrotest tul Schlumberger w Spectoscopy Co RDMO Slumberg	ooler wn bailer bing scanners and ireline. Schlumbe mbo log form 883	d scan tubin erger Run 35' (top of fi	* tbg. SIFWE Operation Mathematical Advances of the second reg OOH. Found 123 YB, 13 #1. Casing collar locator/ CI II) to 7000'. Run #2 Scient ose well in for night.	NL compensate	ed neutron / I	NGS-C Natur	al GR
Dur (hrs) 0.50 safet; 1.00 trip o 3.00 lay dr 1.00 rig ur 4.00 trip in eport Start Date 1/2/2007 1/2/2007	y meeting ut of hole with tubing own esp/rig down sp bailer, tag fill, rig do hole with tubing Last 24hr Summary RU Hydrotest tul Schlumberger w Spectoscopy Co RDMO Slumberg Last 24hr Summary RU Centrilift equ	ooler wm bailer bing scanners an ireline. Schlumbe mbo log form 883 ger and Scientific ipment & assemt tands and cable s	d scan tubii erger Run 55' (top of fi Drilling. Clu ble ESP pui	* tbg. SIFWE Operation Mathematical Advances of the second reg OOH. Found 123 YB, 13 #1. Casing collar locator/ CI II) to 7000'. Run #2 Scient ose well in for night.	NL compensate fic Drilling Gyr	ed neutron / I o survey log hrs on tubing	NGS-Č Natur from 8835' to g pressure te:	al GR surface. sters. Sta
Dur (hrs) 0.50 safet; 1.00 trip o 3.00 lay dr 1.00 rig ur 4.00 trip in eport Start Date 1/2/2007 1/2/2007	y meeting ut of hole with tubing own esp/rig down sp baller, tag fill, rig do hole with tubing Last 24hr Summary RU Hydrotest tul Schlumberger w Spectoscopy Co RDMO Slumberg Last 24hr Summary RU Centrilift equ in hole with 10 si	ooler wm bailer bing scanners an ireline. Schlumbe mbo log form 883 ger and Scientific ipment & assemt tands and cable s	d scan tubii erger Run 55' (top of fi Drilling. Clu ble ESP pui	* tbg. SIFWE Operation mg OOH. Found 123 YB, 13 #1. Casing collar locator/ Cl II) to 7000'. Run #2 Scient ose well in for night. Operation mp. Finish assembly of pur	NL compensate fic Drilling Gyr	ed neutron / I o survey log hrs on tubing	NGS-Č Natur from 8835' to g pressure te:	al GR surface. sters. Sta
Dur (hrs) 0.50 safet; 1.00 trip o 3.00 lay dr 1.00 trip in 4.00 trip in 4.00 trip in 1/2/2007	y meeting ut of hole with tubing own esp/rig down sp bailer, tag fill, rig do hole with tubing Last 24hr Summary RU Hydrotest tul Schlumberger w Spectoscopy Co RDMO Slumberg Last 24hr Summary RU Centrilift equ in hole with 10 si testers broke doo	ooler wm bailer bing scanners an ireline. Schlumbe mbo log form 883 ger and Scientific ipment & assemt tands and cable s	d scan tubii erger Run 55' (top of fi Drilling. Clu ble ESP pui	* tbg. SIFWE Operation ng OOH. Found 123 YB, 13 #1. Casing collar locator/ Cl II) to 7000'. Run #2 Scient ose well in for night. Operation mp. Finish assembly of purk ke down. Wait 2 hours on particular	NL compensate fic Drilling Gyr	ed neutron / I o survey log hrs on tubing	NGS-Č Natur from 8835' to g pressure te:	al GR surface. sters. Sta
Dur (hrs) 0.50 safet; 1.00 trip o 3.00 lay de 1.00 rig up 4.00 trip in eport Start Date 1/2/2007 1/2/2007	y meeting ut of hole with tubing own esp/rig down sp baller, tag fill, rig do hole with tubing Last 24hr Summary RU Hydrotest tul Schlumberger w Spectoscopy Co RDMO Slumberg Last 24hr Summary RU Centrilift equ in hole with 10 si testers broke do	ooler wm bailer bing scanners and ireline. Schlumber mbo log form 883 ger and Scientific ipment & assemt tands and cable s wn. SDFN SP on 2 7/8" N-86	d scan tubin erger Run 55' (top of fi Drilling. Cl Die ESP put pooler brol	* tbg. SIFWE Operation ng OOH. Found 123 YB, 13 #1. Casing collar locator/ Cl II) to 7000'. Run #2 Scient ose well in for night. Operation mp. Finish assembly of purk ke down. Wait 2 hours on particular	NL compensate fic Drilling Gyr ap and wait 1.5 arts and repair.	ed neutron / I o survey log hrs on tubing Ran 5 stand	NGS-Č Natura from 8835' to g pressure tes ds of tubing a pressure test	al GR o surface. sters. Sta nd tubing ers ND B0
Dur (hrs) 0.50 safet; 1.00 trip o 3.00 lay de 1.00 rig up 4.00 trip in eport Start Date 1/2/2007 1/2/2007	y meeting ut of hole with tubing own esp/rig down sp bailer, tag fill, rig do hole with tubing Last 24hr Summary RU Hydrotest tul Schlumberger w Spectoscopy Co RDMO Slumberg Last 24hr Summary RU Centrilift equ in hole with 10 si testers broke do Last 24hr Summary Finish running E NU wellhead, ma	ooler wm bailer bing scanners and ireline. Schlumber mbo log form 883 ger and Scientific ipment & assemt tands and cable s wn. SDFN SP on 2 7/8" N-86	d scan tubin erger Run 55' (top of fi Drilling. Cl Die ESP put pooler brol	* tbg. SIFWE Operation ng OOH. Found 123 YB, 13 #1. Casing collar locator/ Ci ill) to 7000'. Run #2 Scient ose well in for night. Operation mp. Finish assembly of purk ke down. Wait 2 hours on particle Operation 8386 feet while pressure tess	NL compensate fic Drilling Gyr ap and wait 1.5 arts and repair.	ed neutron / I o survey log hrs on tubing Ran 5 stand	NGS-Č Natura from 8835' to g pressure tes ds of tubing a pressure test	al GR o surface. sters. Sta nd tubing ers ND BC
0.50 safet 1.00 trip o 3.00 lay do 1.00 rig up 4.00 trip in teport Start Date 1/2/2007 Fime Log Dur (hrs) teport Start Date 1/3/2007 Fime Log Dur (hrs) teport Start Date 1/3/2007	y meeting ut of hole with tubing own esp/rig down sp bailer, tag fill, rig do hole with tubing Last 24hr Summary RU Hydrotest tul Schlumberger w Spectoscopy Co RDMO Slumberg Last 24hr Summary RU Centrilift equ in hole with 10 si testers broke do Last 24hr Summary Finish running E NU wellhead, ma	ooler wm bailer bing scanners and ireline. Schlumber mbo log form 883 ger and Scientific ipment & assemt tands and cable s wn. SDFN SP on 2 7/8" N-86	d scan tubin erger Run 55' (top of fi Drilling. Cl Die ESP put pooler brol	* tbg. SIFWE Operation Additional Content of the second	NL compensate fic Drilling Gyr ap and wait 1.5 arts and repair.	ed neutron / I o survey log hrs on tubing Ran 5 stand	NGS-Č Natura from 8835' to g pressure tes ds of tubing a pressure test	al GR o surface. sters. Sta nd tubing ers ND BC
Dur (hrs) 0.50 safet 1.00 trip o 3.00 lay de 1.00 rig up 4.00 trip in teport Start Date 1/2/2007 1/2/2007	y meeting ut of hole with tubing own esp/rig down sp baller, tag fill, rig do hole with tubing Last 24hr Summary RU Hydrotest tul Schlumberger w Spectoscopy Co RDMO Slumberg Last 24hr Summary RU Centrilift equ in hole with 10 si testers broke dow Last 24hr Summary Finish running E NU wellhead, ma rig down SDFN Last 24hr Summary	ooler wm bailer bing scanners and ireline. Schlumber mbo log form 883 ger and Scientific ipment & assemt tands and cable s wn. SDFN SP on 2 7/8" N-86	d scan tubin erger Run 55' (top of fi Drilling. Cl Die ESP put pooler brol	* tbg. SIFWE Operation Operation a GOOH. Found 123 YB, 13 #1. Casing collar locator/ Cl II) to 7000'. Run #2 Scient ose well in for night. Operation mp. Finish assembly of purk ke down. Wait 2 hours on pr Operation 8386 feet while pressure tese ed up in XX min. ESP check Operation	NL compensate fic Drilling Gyr ap and wait 1.5 arts and repair.	ed neutron / I o survey log hrs on tubing Ran 5 stand	NGS-Č Natura from 8835' to g pressure tes ds of tubing a pressure test	al GR o surface. sters. Sta nd tubing ers ND BC
Dur (hrs) 0.50 safet; 1.00 trip o 3.00 lay dr 1.00 rig ur 4.00 trip in eport Start Date 1/2/2007 1/2/2007	y meeting ut of hole with tubing own esp/rig down sp baller, tag fill, rig do hole with tubing Last 24hr Summary RU Hydrotest tul Schlumberger w Spectoscopy Co RDMO Slumberg Last 24hr Summary RU Centrilift equ in hole with 10 si testers broke dow Last 24hr Summary Finish running E NU wellhead, ma rig down SDFN Last 24hr Summary	ooler wm bailer bing scanners and ireline. Schlumber mbo log form 883 ger and Scientific ipment & assemt tands and cable s wn. SDFN SP on 2 7/8" N-86	d scan tubin erger Run 55' (top of fi Drilling. Cl Die ESP put pooler brol	* tbg. SIFWE Operation Additional Content of the second	NL compensate fic Drilling Gyr ap and wait 1.5 arts and repair.	ed neutron / I o survey log hrs on tubing Ran 5 stand	NGS-Č Natura from 8835' to g pressure tes ds of tubing a pressure test	al GR o surface. sters. Sta nd tubing ers ND BC
Dur (hrs) 0.50 safet 1.00 trip o 3.00 lay de 1.00 rig up 4.00 trip in eport Start Date 1/2/2007 1/2/2007 Fime Log Dur (hrs) 1/3/2007 Fime Log Dur (hrs) 1/4/2007 Fime Log Dur (hrs) 1/4/2007 Fime Log Dur (hrs) 1/4/2007	y meeting ut of hole with tubing own esp/rig down sp baller, tag fill, rig do hole with tubing Last 24hr Summary RU Hydrotest tul Schlumberger w Spectoscopy Co RDMO Slumberg Last 24hr Summary RU Centrilift equ in hole with 10 si testers broke dow Last 24hr Summary Finish running E NU wellhead, ma rig down SDFN Last 24hr Summary	ooler wm bailer bing scanners and ireline. Schlumber mbo log form 883 ger and Scientific ipment & assemt tands and cable s wn. SDFN SP on 2 7/8" N-86	d scan tubin erger Run 55' (top of fi Drilling. Cl Die ESP put pooler brol	* tbg. SIFWE Operation Operation a GOOH. Found 123 YB, 13 #1. Casing collar locator/ Cl II) to 7000'. Run #2 Scient ose well in for night. Operation mp. Finish assembly of purk ke down. Wait 2 hours on pr Operation 8386 feet while pressure tese ed up in XX min. ESP check Operation	NL compensate fic Drilling Gyr ap and wait 1.5 arts and repair.	ed neutron / I o survey log hrs on tubing Ran 5 stand	NGS-Č Natura from 8835' to g pressure tes ds of tubing a pressure test	al GR o surface. sters. Sta nd tubing ers ND B0

.