Form 3160-5 (April2004)

UNITEDSTATES OCD-HORRS DEPARTMENT OF THE INTERIOR

」 Casing Repair

Change Plans

☐ Convert to Injection

FORMAPPROVED OM B No. 1004-0137 Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				5. Lease Serial No. NM 029489A 6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side. Type of Well				7. If Unit or CA/Agreement, Name and/or No-NMNM84603X 8. Well Name and No. Central Corbin Queen Unit #406 9. API Well No. 30-025-36870 36868
. Type of Well Soil Well				
50' FNL & 2480' FWL Sec 9, T18S, R33E				11. County or Parish, State Lea NM
12. CHECK AF	PPROPRIATE BOX(E	S)TO INDICATE NATU	RE OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
Noticeof Intent	Acidize AlterCasing	Deepen FractureTreat	Production (Sta	art/Resume) Water Shut-Off Well Integrity

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

New Construction

Plug and Abandon

PlugBack

Recomplete

X Temporarily Abandon

Latigo Petroleum, Inc. respectfully request TA approval for future utility in an existing secondary recovery project.

1. Set CIBP @ 4200' and run MIT.

Subsequent Report

Final Abandonment Notice

SEE ATTACHED FOR CONDITIONS OF APPROVAL Hpproval for

I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title Regulatory Analyst Lisa Hunt 01/25/2007 Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Central Corbin Queen Unit #406 Latigo Petroleum, Inc POGO Producing Company January 31, 2007 Conditions of Approval

Conditions of Approval are based on telephone conversation with Rex Jasper of POGO Producing Company on 1/31/2007 at 1516 hours.

- 1. Sundry noting change of operator is needed.
- 2. TA request for Central Corbin Queen Unit #406; justification based on fact that property was purchased from Latigo Petroleum, Inc in 2006 and POGO Producing Company is requesting adequate time to evaluate the property regarding potential bypassed reserves. Request is for a three year period beginning January 31, 2007.
- 3. Approval is given to perform an MIT.
- 4. Attached are the additional conditions required for granting a TA.
- 5. When those conditions are met, a TA will be approved for a 12 month period.

WWI 013107

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 505-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 505-361-2822; Lea County 505-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for a 12 month period provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.

The TA status could be extended for an additional 12 month period without another casing integrity test provided there was no leak-off during the test and the test was witnessed by a BLM representative. The operator must submit a sundry notice requesting an extension of TA status 30 days prior to expiration of the previous approval and appropriate justification for extending the TA status is included.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

WWI 11022006