

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
May 27, 2004

WELL API NO.

30-025-08658

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

E-396

7. Lease Name or Unit Agreement Name
Cone Jalmat Pool Unit

8. Well Number 804

9. OGRID Number 184860

10. Pool name or Wildcat
Jalmat-Tansill Yates Seven River

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other Water Injection

2. Name of Operator
Melrose Operating Company, LLC

3. Address of Operator 5813 NW Grand Blvd Suite B
Oklahoma City, OK 73118

4. Well Location

Unit Letter K : 1980 feet from the north line and 1980 feet from the north line
Section 25 Township 22S Range 35E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc)
3580

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest freshwater well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1-11-07 MIRUPU, & reverse unit, clean out 5 1/2" casing to PBTD, 3956'.


1-12-07 Rig up wireline & run casing inspection log, found bad casing, RD WL, RDPU.

2-12-07 MIRUPU, RIH w/88 jnts 4" Ultra Flush Jnt 9.50# casing, set at 3909', RDPU

2-24-07 RU & cement 4" liner w/ 300sx class "C", cement, circulate cement to surface, RD cementers

2-27-07 RU Wireline & run CBL, CCL, GR, found cement at surface, Perf Yates zone: 3714-19, 22-24, 26-28, 40-46, 58-72, 3812-32, 48-52, w/4SPF, 212 holes, RD WL.

2-28-07 MIRUPU, RIH w/4" Baker AD-1 Nickle coated packer & 117 jnts 2 3/8", J-55, 8rd, Duoline 20 tubing, RU & circ. Packer fluid around pkr & csg., set packer in tension at 3660', RU & test csg & pkr to 300#s for 1 min., OK, 800 & MO



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Anthony Beilman TITLE Operation Supt DATE 02/27/2007

Type or print name Anthony Beilman

E-mail address: trinityengineering@sbcglobal.net Telephone No. (405)848-4012

For State Use Only

OC FIELD REPRESENTATIVE II/STAFF MANAGER MAR 07 2007

APPROVED BY: Hayward Wink TITLE _____ DATE _____

Conditions of Approval (if any): _____

