<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For drilling and production facilities, submit to appropriate NMOCD District Office.

For downstream facilities, submit to Santa Fe

Form C-144

June 1, 2004

office

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes ☐ No ☒ Type of action: Registration of a pit or below-grade tank ☐ Closure of a pit or below-grade tank ☒		
Operator: B. C. Operating, Inc. Telephone: 4	432) 684-9696 e-mail address:	
Address: P. O. Box 50820 Midland, TX 79710	7.000	
Facility or well name:		Sec 21 T 16S R 33E
1	706.259 Longitude <u>692.394</u>	NAD: 1927 ⊠ 1983 ☐
Surface Owner: Federal State Private Indian		
<u>Pit</u>	Below-grade tank	
Type: Drilling ☑ Production ☐ Disposal ☐	Volume:bbl Type of fluid: Construction material: Double-walled, with leak detection? Yes If not, explain why not.	
Workover Emergency	Construction material:	
Lined 🖾 Unlined 🗔	Double-walled, with leak detection? Yes If not, explain why not.	
Liner type: Synthetic ☑ Thickness 14 mil Clay ☐		
Pit Volume <u>24,000</u> bbl		
Depth to ground water (vertical distance from bottom of pit to seasonal	Less than 50 feet	(20 points)
	50 feet or more, but less than 100 feet	(10 points)
high water elevation of ground water.) $GW = 144$	100 feet or more	(0 points) XXX
	37	9101112737
Wellhead protection area: (Less than 200 feet from a private domestic	Yes	(20 points)
water source, or less than 1000 feet from all other water sources.)	No	(0 points XXX
District Control of the Control of t	Less than 200 feet	(20 points)
Sistance to surface water: (horizontal distance to all wetlands, playas,	200 feet or more, but less than 1000 feet	(10 points) Received
gation canals, ditches, and perennial and ephemeral watercourses.)	1000 feet or more	(() nointe) XXX Fluid
		OCD A
	Ranking Score (Total Points)	0 Points
If this is a pit closure: (1) Attach a diagram of the facility showing the pit's		
If this is a pit closure: (1) Attach a diagram of the facility showing the pit's your are burying in place) onsite ☑ offsite ☐ If offsite, name of facility	s relationship to other equipment and tanks. (2) Indie	cate disposal location consider the obsite box if
your are burying in place) onsite \square offsite \square If offsite, name of facility	s relationship to other equipment and tanks. (2) India	cate disposal location Color Baconsite box if description of remedial action taken including
	s relationship to other equipment and tanks. (2) India (3) Attach a general Yes [If yes, show depth below ground surface	cate disposal location Color Baconsite box if description of remedial action taken including
your are burying in place) onsite ⊠ offsite □ If offsite, name of facility remediation start date and end date. (4) Groundwater encountered: No ⊠ Y	s relationship to other equipment and tanks. (2) India (3) Attach a general (4) If yes, show depth below ground surface tions.	cate disposal location colors acoustic box if description of remedial action taken including ft. and attach sample results.
your are burying in place) onsite offsite foffsite, name of facility	s relationship to other equipment and tanks. (2) Indie (3) Attach a general Yes [If yes, show depth below ground surface tions. pervious liner. The drilling pit contents were mixed yes.	cate disposal location dispersion of remedial action taken including ft. and attach sample results. with stockpiled soil to stiffen the mud and
your are burying in place) onsite offsite foffsite, name of facility	s relationship to other equipment and tanks. (2) India (3) Attach a general (4) If yes, show depth below ground surface tions. Dervious liner. The drilling pit contents were mixed weated. The analytical and plat map are attached. As	cate disposal location colors and stee box if description of remedial action taken including ft. and attach sample results. with stockpiled soil to stiffen the mud and per the risk based approval from Chris Williams
your are burying in place) onsite offsite If offsite, name of facility_remediation start date and end date. (4) Groundwater encountered: No	s relationship to other equipment and tanks. (2) India (3) Attach a general (4) If yes, show depth below ground surface tions. Dervious liner. The drilling pit contents were mixed vertex. As a capped with a 20 mil impervious liner.	cate disposal location colors and stee box if description of remedial action taken including ft. and attach sample results. with stockpiled soil to stiffen the mud and per the risk based approval from Chris Williams
your are burying in place) onsite offsite If offsite, name of facility_remediation start date and end date. (4) Groundwater encountered: No (5) Attach soil sample results and a diagram of sample locations and excavated Additional Comments: A burial was excavated and lined with a 12 mil imp placed in the burial pit. The bottom of the drilling pit was tested and deline the contamination was left in place and capped with a 20 mil liner. The burial pit.	s relationship to other equipment and tanks. (2) India (3) Attach a general (4) If yes, show depth below ground surface tions. Dervious liner. The drilling pit contents were mixed vertex. As a capped with a 20 mil impervious liner.	cate disposal location colors and stee box if description of remedial action taken including ft. and attach sample results. with stockpiled soil to stiffen the mud and per the risk based approval from Chris Williams
your are burying in place) onsite offsite foffsite, name of facility_remediation start date and end date. (4) Groundwater encountered: No	s relationship to other equipment and tanks. (2) India (3) Attach a general (4) If yes, show depth below ground surface tions. Dervious liner. The drilling pit contents were mixed vertex. As a capped with a 20 mil impervious liner.	cate disposal location colors and stee box if description of remedial action taken including ft. and attach sample results. with stockpiled soil to stiffen the mud and per the risk based approval from Chris Williams
your are burying in place) onsite offsite foffsite, name of facility	s relationship to other equipment and tanks. (2) India (3) Attach a general Yes If yes, show depth below ground surface tions. Dervious liner. The drilling pit contents were mixed yeated. The analytical and plat map are attached. As rial pit was also capped with a 20 mil impervious line pooling.	cate disposal location colors and object to box if description of remedial action taken including ft. and attach sample results. with stockpiled soil to stiffen the mud and per the risk based approval from Chris Williams er 3' below ground surface and overlaping 3' in
your are burying in place) onsite offsite foffsite, name of facility	s relationship to other equipment and tanks. (2) India (3) Attach a general Yes If yes, show depth below ground surface tions. Dervious liner. The drilling pit contents were mixed yeated. The analytical and plat map are attached. As rial pit was also capped with a 20 mil impervious line pooling.	cate disposal location colors and object to box if description of remedial action taken including ft. and attach sample results. with stockpiled soil to stiffen the mud and per the risk based approval from Chris Williams er 3' below ground surface and overlaping 3' in
your are burying in place) onsite offsite foffsite, name of facility_remediation start date and end date. (4) Groundwater encountered: No (5) Attach soil sample results and a diagram of sample locations and excavated Additional Comments: A burial was excavated and lined with a 12 mil imp placed in the burial pit. The bottom of the drilling pit was tested and deline the contamination was left in place and capped with a 20 mil liner. The but all directions. Clean native soil was then backfilled and doomed to prevent lines been/will be constructed or closed according to NMOCD guidelines. Date: 5/8/07	s relationship to other equipment and tanks. (2) India (3) Attach a general Yes If yes, show depth below ground surface tions. Dervious liner. The drilling pit contents were mixed yeated. The analytical and plat map are attached. As rial pit was also capped with a 20 mil impervious line pooling.	cate disposal location colors and object to box if description of remedial action taken including ft. and attach sample results. with stockpiled soil to stiffen the mud and per the risk based approval from Chris Williams er 3' below ground surface and overlaping 3' in
your are burying in place) onsite offsite offsite, name of facility remediation start date and end date. (4) Groundwater encountered: No offsite offsite, name of facility remediation start date and end date. (4) Groundwater encountered: No offsite offsite, name of facility remediation start date and end date. (4) Groundwater encountered: No offsite offsite, name of facility remediations and excavated and lined with a 12 mil importance of the burial pit. The bottom of the drilling pit was tested and deliming the contamination was left in place and capped with a 20 mil liner. The burial directions. Clean native soil was then backfilled and doomed to prevent all directions. Clean native soil was then backfilled and doomed to prevent has been/will be constructed or closed according to NMOCD guidelines. Date: 5/8/07 Printed Name/Title Regarder Black Reference.	s relationship to other equipment and tanks. (2) India (3) Attach a general (4) If yes, show depth below ground surface tions. Dervious liner. The drilling pit contents were mixed vertical and plat map are attached. As a rial pit was also capped with a 20 mil impervious line pooling. The drilling pit contents were mixed vertical pit was also capped with a 20 mil impervious line pooling. The drilling pit contents were mixed vertically a series of my knowledge and belief. I further certify that is a general permit , or an (attached) alternated the signature and series of the signature and series of the signature and series of the signature.	cate disposal location college to be box if description of remedial action taken including ft. and attach sample results. with stockpiled soil to stiffen the mud and per the risk based approval from Chris Williams er 3' below ground surface and overlaping 3' in the above-described pit or below-grade tank ative OCD-approved plan .
your are burying in place) onsite offsite foffsite, name of facility_remediation start date and end date. (4) Groundwater encountered: No (5) Attach soil sample results and a diagram of sample locations and excavated Additional Comments: A burial was excavated and lined with a 12 mil implaced in the burial pit. The bottom of the drilling pit was tested and deline the contamination was left in place and capped with a 20 mil liner. The burial directions. Clean native soil was then backfilled and doomed to prevent all directions. Clean native soil was then backfilled and doomed to prevent has been/will be constructed or closed according to NMOCD guidelines.	s relationship to other equipment and tanks. (2) India (3) Attach a general (4) If yes, show depth below ground surface tions. Dervious liner. The drilling pit contents were mixed vertical and plat map are attached. As arial pit was also capped with a 20 mil impervious line pooling. Of my knowledge and belief. I further certify that is a general permit , or an (attached) alternation of relieve the operator of liability should the contents.	cate disposal location color accounts box if description of remedial action taken including ft. and attach sample results. with stockpiled soil to stiffen the mud and per the risk based approval from Chris Williams er 3' below ground surface and overlaping 3' in the above described pit or below-grade tank ative OCD-approved plan .
your are burying in place) onsite offsite foffsite, name of facility remediation start date and end date. (4) Groundwater encountered: No (5) Attach soil sample results and a diagram of sample locations and excavated Additional Comments: A burial was excavated and lined with a 12 mil imp placed in the burial pit. The bottom of the drilling pit was tested and deline the contamination was left in place and capped with a 20 mil liner. The buall directions. Clean native soil was then backfilled and doomed to prevent has been/will be constructed or closed according to NMOCD guidelines. Date: 5/8/07 Printed Name/Title	s relationship to other equipment and tanks. (2) India (3) Attach a general (4) If yes, show depth below ground surface tions. Dervious liner. The drilling pit contents were mixed vertical and plat map are attached. As arial pit was also capped with a 20 mil impervious line pooling. Of my knowledge and belief. I further certify that is a general permit , or an (attached) alternation of relieve the operator of liability should the contents.	cate disposal location color accounts box if description of remedial action taken including ft. and attach sample results. with stockpiled soil to stiffen the mud and per the risk based approval from Chris Williams er 3' below ground surface and overlaping 3' in the above described pit or below-grade tank ative OCD-approved plan .