Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103		
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources			WELL API NO.		
District II	OIL CONSERVATION DIVISION				30-025-06752	
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.			5. Indicate Type STATE	e of Lease FEE X	5
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			6. State Oil & G		
1220 S. St. Francis Dr., Santa Fe, NM 87505		ŕ		0. 5	20000110.	
The state of the s	CES AND REPORTS	ON WELLS	<u> </u>	7. Lease Name of	or Unit Agreement Na	me
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Northeast Drinkard Unit		
1. Type of Well: Oil Well Gas Well OtherWater Injector				8. Well Number 902		
2. Name of Operator Apache Corporation				9. OGRID Number 00873		
3. Address of Operator 6120 S Yale Ave, Suite 1500				10. Pool name or Wildcat		
Tuisa, OK. 74130-4224				Eunice; Blinebry-Tubb-Drinkard, North		
4. Well Location	2000	C41-		.50		
		ne South			om the West	_line
Section 22	Township :		ange 37E	NMPM	CountyLea	
	3413.5' GR	Wilciner Dit,	inder, RT, OR, etc.			
Pit or Below-grade Tank Application on	 					
Pit typeDepth to Groundwa				tance from nearest sur	face water	
Pit Liner Thickness: mil	Below-Grade Tank:	Volume	bbls; C	onstruction Material	· · · · · · · · · · · · · · · · · · ·	
12. Check A	ppropriate Box to	Indicate N	ature of Notice,	Report or Other	r Data	
NOTICE OF IN	TENTION TO:		SUE	SEQUENT RE	PORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR					ALTERING CASING	€ 🗆
TEMPORARILY ABANDON					P AND A]
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMEN	T JOB 🗌		
OTHER:			OTHER:Casing I	ntegrity Test - Wate	er Injector Well	X
13. Describe proposed or compl	eted operations. (Clea	rly state all p	pertinent details, an	d give pertinent dat	tes, including estimate	d date
of starting any proposed wo or recompletion.	rk). SEE RULE 1103.	For Multip	le Completions: A	tach wellbore diag	ram of proposed comp	oletion
1. Tagged fill @ 6560'. Cleaned out	fill to TD @ 7502'.					
2. Replaced all seals on duo lined tb3. Set pkr @ 3873.4'.	g.					
4. Notified Sylvia Dickey OCD1-FO	O1 of casing integrity	test.		بيار	7-123	
5. Ran MIT 5/16/2007 and passed.				1	h .	
MIT chart attached.				15	" ©	
				180		
					144	
					3	
					Cal.	
•						
I hereby certify that the information a grade tank has been/will be constructed or c	bove is true and comp losed according to NMOC	lete to the be	est of my knowledg], a general permit [e and belief. I furth or an (attached) altern	er certify that any pit or l native OCD-approved pla	below- n [].
SIGNATURE LOPPICE	Mackay	_TITLE_Eng	ineering Tech		DATE 05/23/2007	
Type or print name Sophie Mackay For State Use Only	/				alephone No. (918)49	1-4864
0/ /.	1,1-1	OC FIELD		IVSTAFF MANAC	GER MAY 252	007
APPROVED BY: Jay (1) Conditions of Approval (if any):	WIND	_TITLE			DATE	

