

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis, Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised May 08, 2003

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-29777
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other WIW <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator SAGA PETROLEUM LLC		6. State Oil & Gas Lease No. Federal Unit Agreement NM84603X
3. Address of Operator 415 W WALL, SUITE 1900 MIDLAND, TX 79701		7. Lease Name or Unit Agreement Name CENTRAL CORBIN QUEEN UNIT
4. Well Location Unit Letter C : 660 feet from the N line and 1980 feet from the W line Section 4 Township 18S Range 33E NMPM County LEA		8. Well Number 209
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3984.8 GR		9. OGRID Number 148967
10. Pool name or Wildcat Corbin Queen, Central		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOBS ☐

OTHER: MIT after workover ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8-15-2003 Annulus comm w/tbg-Bleed well to pit. NDWH & NU BOP, release pkr & POOH w/112 jts - 2 small HITS, LD) continue out w/17 jts & AD-1 pkr. PU new 2-3/8"x5-1/2" AD-1 pkr & RIH on 129 jts 2-3/8" cmt lined tbg. ND BOP & NUWH. RU pump trk & circ 94 bbls pkr fluid. Set pkr w/13 pts tension.

Test annulus & pkr to 560 psi for 30 mins-good. RD pump trk

Chart attached

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Production Analyst DATE 09/18/2003

Type or print name Bonnie Husband

Telephone No. (432)684-4293

(This space for State use)

APPROVED BY

FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

Conditions of approval, if any:

SEP 23 2003

