District I 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210 - <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Energy Mi Oil (1220 Sa	ate of New Mexico inerals and Natural Resources Conservation Division South St. Francis Dr. anta Fe, NM 87505	For drilling and product appropriate NMOCD Dist For downstream facilitie office	Form C-144 June 1, 2004 ion facilities, submitto rict Office. s, submit to Santa Fe
Is pit	or below-grade tan	ade Tank Registration or (k covered by a "general plan"? Yes r below-grade tank Closure of a pit or b	No.	
Operator: LEWIS B. BURLESON, INC. Address: P.O. BOX 2479 MIDLAND, TI		e: (432)683-4747e-mail address: GEC 5-37387 U/Ior Qtr/Qtr_N Sec 2	DTTECH@PRODIGY. 22 T 228 R 37E	
<u>Pit</u>	110011	Below-gradetank		
Type: Drilling X Production Disposal Workover Emergency	LEGAL	Volume:bbl Type of fluid: Construction material:		
	t	Double-walled, with leak detection? Yes		
Liner type: Synthetic Thickness 6 mil Clay				- 3150-60
Pit Volume 1100 bb				050-0
Depth to ground water (vertical distance from bottom	of pit to seasonal high	Less than 50 feet	(20 points)	
water elevation of ground water.)		50 feet or more, but less than 100 feet 100 feet or more	(10 points)	10
			(0 points)	
Wellhead protection area: (Less than 200 feet from a private domes		Yes	(20 points)	N
water source, or less than 1000 feet from all other wa	ter sources.)	No	(0 points)	0
Distance to surface water: (horizontal distance to all	wetlands, playas,	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(10 points) (0 points))021	02324 2324
·		RankingScore (Total Points)	101	33
If this is a pit closure (1) attacha diagram of the figure of the figure of the second	fsite, name of facility \underline{S} rencountered: No \underline{X} Y	UNDANCE (3) Attach a /es If yes, show depth below ground sur	general description of remedi faceft.and.aft	Check the onsite box if alaction taken including ach sample results (5)
AdditionalComments:		and a second and a s	<u> </u>	a the
STARTED HAUL TO SUNDANCE API	RIL 28, 2006. CO	LLECTED BOTTOM SAMPLES	5/2/06. SAMPLÈS WI	RÉ-GÓOD.
CONTRACTOR LEVELED		<u> </u>		
PIT BACK TO CONTOUR 7/6/2006. F	NAL REPORT OI	F CLOSURE 7/10/2006.	SAMPLES NO	T HTTACHED.
			······	
I hereby certify that the information above is true an been/will be constructed or closed according to N Date: <u>07/11/2006</u> Printed Name/Title STEVEN L. BURLESO Your certification and NMOCD approval of this app	MOCD guidelines (3), N,-VICE-PRESIDI lication/closuredoes not	a general permit [], or an (attached) alter ENSignature t relieve the operator of liability should the c	rnativeOCD-approvedplan	minate ground water or
otherwise endanger public health or the environmen regulations:	t. Nor does it relieve the	e operator of its responsibility for compliance	e with any other federal, state,	or local laws and/or
Approval: ACCEPTED FOR REG Printed Name/Title L JP Hasson -		Signature		6.27.07

•

.

,

/



Sample Locations

7/10/06