

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-14
March 12, 200

For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes ☒ No ☐

Type of action Registration of a pit or below-grade tank ☐ Closure of a pit or below-grade tank ☒

Operator: **Marbob Energy Corporation**

Telephone: **505-748-3303**

e-mail address: **land2@marbob.com**

Address: **PO Box 227, Artesia, NM 88211-0227**

1980' FNL & 1980' FWL

Facility or well name **Scooch State Com #1**

API #: **30-025-36995**

U/L or Qtr/Qtr **SENW** Sec **23** T **18S** R **33E**

County: **Lea**

Latitude _____ Longitude _____

NAD 1927 ☐ 1983 ☐ Surface Owner Federal ☐ State ☒ Private ☐ Indian ☐

Pit

Type: Drilling ☒ Production ☐ Disposal ☐

Workover ☐ Emergency ☐

Lined ☒ Unlined ☐

Liner type Synthetic ☒ Thickness **12** mil Clay ☐ Volume

_____ bbl

Below-grade tank

Volume: _____ bbl Type of fluid: _____

Construction material: _____

Double-walled, with leak detection? Yes ☐ If not, explain why not: _____

Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water)

Less than 50 feet

50 feet or more, but less than 100 feet

100 feet or more

(20 points)

(10 points)

(0 points)

Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)

Yes

No

(20 points)

(0 points)

0 points

Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses)

Less than 200 feet

200 feet or more, but less than 1000 feet

1000 feet or more

(20 points)

(10 points)

(0 points)

0 points

Ranking Score (Total Points)

0 points

If this is a pit closure: (1) attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location.

onsite ☐ offsite ☒ If offsite, name of facility **Sundance Disposal** (3) Attach a general description of remedial action taken including remediation start date and end date (4) Groundwater encountered: No ☒ Yes ☐ If yes, show depth below ground surface _____ ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavations. ***Drilled 65' test hole at 865' FNL & 1650' FWL Sec 23-T18S-R33E. No water encountered.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general plan ☒, or an (attached) alternative OCD-approved plan ☒. **INFO INCONCLUSIVE DUE TO PROCS**

Date: **June 6, 2007**

Printed Name/Title: **Gerald Herrera**

Signature *G. Herrera*

Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations.

Approval: *Dig & Herrera*

Date: **6-13-07**

Printed Name/Title: **JOHNSON, ENRIQUE ENRIQUE**

Signature *Enrique Johnson*

Sampling was completed as stipulated. Attached are the analysis and pit was closed on 8/6/07

Raul Lopez

Samples are to be obtained from pit floor area in each quadrant and analysis submitted to NMOCD prior to back-filling. (Chloride)

Marbob Energy Corporation
Attachment to OCD Form C-144


Pit or Below-Grade Tank Registration or Closure

Pit Closure

Scooch State Com #1

1980' FNL & 1980' FWL
Section 23 T-18S R-33E
Lea County, New Mexico

(1) Facility diagram



(2) Disposal location:

Truck and haul cuttings to Sundance Disposal.

(3) General description of remedial action:

- Use caliche from road and pad to fill pit.*
- Use stock piled dirt to cover pit, reseed per landowner's specifications.*

(4) Groundwater encountered:

No

- * **Drilled an 80' test hole on the Rhoid State #1 well at 330' FNL & 330' FWL
Section 24 T-18S R-33E - Water leached into hole to 62'.
Well Record submitted previously**

(5) Soil sample:

Marbob
~~N/A~~ *SAMPLE PCT FOR CHLORIDE - CLEAN TO 250 PPM*
& REMOVE - SUBMIT SAMPLE DATA w/ CLOSURE



PHONE (915) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
BBC INTERNATIONAL, INC
ATTN: CLIFF BRUNSON
P.O. BOX 805
HOBBS, NM 88241
FAX TO: (505) 397-0397


Receiving Date: 07/27/07
Reporting Date: 07/30/07
Project Owner: MARBOB
Project Name: SCOCH STATE #1
Project Location: MALJAMAR, NM

Analysis Date: 07/27/07
Sampling Date: 07/26/07
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: AB
Analyzed By: HM

LAB NO.	SAMPLE ID	Cl ⁻ (mg/Kg)
H12994-1	PIT BOTTOM	96
Quality Control		500
True Value QC		500
% Recovery		100
Relative Percent Difference		2.0

METHOD: Standard Methods	4500-Cl ⁻ B
--------------------------	------------------------

Note: Analysis performed on a 1:4 w/v aqueous extract


Chemist

07-30-07
Date

H12994 BBC

PLEASE NOTE: Liability and Damages: Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.

ARDINAL LABORATORIES, INC.

2111 Beechwood, Abilene, TX 79603 101 East Marland, Hobbs, NM 88240
(915) 673-7001 Fax (915) 673-7020 (505) 393-2326 Fax (505) 393-2476

(915) 673-7001 Fax (915) 673-7020 (505) 393-2326 Fax (505) 393-2476

Page 1

[illegible]