

District I  
1625 N. French Dr , Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Devon Energy Production Company, LP	Contact <input type="checkbox"/> Roger Hernandez
Address. Box 250, Artesia, NM 88211	Telephone No. <input type="checkbox"/> (505) 748-3371
Facility Name Outland State Un 1Y	Facility Type <input type="checkbox"/> Producing Gas Well <u>3002534818000</u>

Surface Owner <u>~100'</u>	Mineral Owner <u>STB</u>	Lease No. <input type="checkbox"/>
----------------------------	--------------------------	------------------------------------

#### LOCATION OF RELEASE

Unit Letter <u>SM</u>	Section 12	Township 021S	Range 034E	Feet from the 638	North/South Line South	Feet from the 739	East/West Line West	County Lea County, NM
-----------------------	------------	---------------	------------	-------------------	------------------------	-------------------	---------------------	-----------------------

#### NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 60	Volume Recovered <input type="checkbox"/> 0
Source of Release 500 bbl Produced Water Tank	Date and Hour of Occurrence 7-21-07 4:00 PM	Date and Hour of Discovery 7-21-07 4:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton - NMOCD	
By Whom? <input type="checkbox"/> Roger Hernandez	Date and Hour <input type="checkbox"/> July 23, 2007 7:20 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

#### Describe Cause of Problem and Remedial Action Taken.\*

Tank battery was struck by lightening resulting in fire and damaged 500 bbl stock tank and produced water tank. resulting in a 60 bbl produced water spill. Stock tank was empty.

**\* NEED CHLORIDE CONTENT OF SPILLED WATER**

#### Describe Area Affected and Cleanup Action Taken.\*

All water was contained inside berm.

**\* NEED TO DETERMINE DEPTH OF CONTAMINATION INSIDE OF BERM**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature. <u>Roger Hernandez</u>	OIL CONSERVATION DIVISION	
Printed Name: Roger Hernandez	INITIAL <u>Johnson</u>	Approved by <input type="checkbox"/> District Supervisor
Title: Production Foreman	Approval Date. <u>10-24-07</u>	Expiration Date: <u>12-31-07</u>
Date: 9-11-07 Phone: 748-5238	Conditions of Approval: <u>SEE * FOR REQUIRED INFO</u>	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

**SUBMIT DELINEATION BY RP#1633**



# Incident Report Form

Version date: 11/18/2004

00014809

Division WESTERN DIVISION

Project PB NEW MEXICO

Field WILSON (NM)

Involvement Property Only

Incident Type Fire, Spill

## 1. Reporting Information

Devon Supervisor: Roger Hernandez

Office Phone: 505-748-3371

Cell Phone: 505-748-5238

Report Date: July 23, 2007

Report Time (am / pm):

6:28:00 PM

Name and Title Reporting:

Roger Hernandez, Production Foreman

Phone: 505-748-0169

Name and title of person that discovered the incident:

Eunice Fire Department

Time and date incident discovered/occurred:

Date: July 21, 2007

Time (am / pm):

4:00 PM

## 2. Summary of What Happened?

Tank battery was struck by lightning resulting in fire and damaged 500 bbl stock tank and produce water tank. Resulting in a 60 bbl produce water spill. Stock tank was empty.

Working Activity:

Operations - Production

Incident Related To:

None of the above

## 3. Contractor Information

Contractor Co. Name:

Address:

Contact

Phone:

Title:

## 4. Location

Location: (name/description)

Outland State

OCSG #:

Pipeline/Well #: 1Y

State: N.M.

Area/Blk#:

Country: U.S.

County/Parish:

Lea, N.M.

Qtr./Qtr Sec.:

Section:

Township:

Range:

Longitude:

Latitude:

Rig#:

Nearest Town, (name, distance and direction from incident):

## 5. Injury/Illness (Employee Or Contractor):

Name of Affected:

Years of Experience:

Work Telephone #:

Home #:

Occupation:

How were they injured?

Primary Body Part

Injured:

List other body parts:

Witness Name:

Witness Telephone #:

Was the affected person transported for treatment?

If yes, complete Hospital/Doctor information

Hospital Name, Addr, Phone

Doctor Name, Addr, Phone

Describe Treatment:

(if known)

Injury Class:

Injury Type:

Illness Type:

Equipment:

## 6. Spills and Air Releases

Factor Contributing to Spill:

Weather Related

Material Released:

Water

Quantity Released:

Oil

Water

60

Quantity

Oil

Water

0

(report all liquids in Bbls)

Chemical

Other

Recovered

Chemical

Other

Size of the affected area:

Contained inside berm

Chemicals spilled:

Time of air release:

Start:

End:

List Gases released:

Describe Area, Property, and Wildlife impacted:

None, tank battery pad

Describe Immediate Actions taken:

Shut well in.

Qty of Air Released

Units

**7. Vehicle Incident**

Driver's Name:	Driver's License #:	DL State:
Devon Vehicle No.:	If injuries, complete no. 5 above and/or no. 10 below.	
Witness Name:	Witness Phone #:	
Was the incident covered by DOT?	Accident Type	
Was a Citation issued?	If YES, to whom was it issued?	

**8. Preventive/Corrective Actions**

PIC: Roger Hernandez

Item	Preventative/Corrective Action	Corrective Actions Taken	Dvn Responsible Emp.	Due Date	Completion Date
1	Unpreventable; had grounding system in place. Tanks were grounded from thief hatch down to a 8' ground rod inserted in the ground.	Evaluate for additional grounding system depending on production and see if its cost effective	Roger Hernandez	12/30/2007	
2					
3					
4					
5					

**9. Weather/Site Conditions**

Describe conditions of ground: Wet			
Describe Sea conditions: Wave Height:		Direction:	Current Speed: Direction:
Temperature: (F)	80	Describe Weather: Rainy	
Wind Speed:	Direction:	Did the weather affect this incident? Yes	

**10. Third Party Involvement**

Driver's Name:	Driver's Phone #:	
Driver's License #:	Licensing State:	
Vehicle License #:	Licensing State:	
Insurance Co. Name:	Insurance Co. Phone #:	
Insurance Policy #:	Trucking Co. Name:	State PUC #

**11. Notifications**

Date	Person/Agency Notified	Time	Phone Number	Fax Number
7/23/2007	NMOCD, Lea County, Pat Caperton	7:20 AM	505-393-6161 Ext-101	
7/21/2007	Linda Berryman	4:30 PM	505-513-0534	
7/21/2007	Don Mayberry	3:30 PM	505-748-5235	

**12. Summary of Classes**

Incident Type	Class
Property Damage	Class III - \$25,000 - \$250,000 or potential insurance claim

EHS Dept.	Linda Berryman	Date:	7/23/2007
Level of Investigation:			