

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Fasken Oil and Ranch, Ltd.	Contact	Jimmy D. Carlile
Address	303 W. Wall, Ste 1800 Midland, TX	Telephone No.	432 687-1777
Facility Name	Denton SWD Battery	Facility Type	Salt water disposal
Surface Owner	Darr Angell	Mineral Owner	Fee
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	13	15S	37E					Lea

Latitude

Longitude

NATURE OF RELEASE

API # 30025053090000

Type of Release	Produced water	Volume of Release	780	Volume Recovered	740
Source of Release	Injection valve	Date and Hour of Occurrence	Date and Hour of Discovery		
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	10/28 1 am	10/28 9:30 am	
By Whom?	Jimmy Carlile	Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted. Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

4" valve was closed and did not hold. The valve has been replaced. We are reviewing the need to replace the existing manifold system inside the battery area.

Describe Area Affected and Cleanup Action Taken.*

Produced water was contained within the diked area. Vacuum trucks were called in and removed 740 barrels of water. Since the area is inside the existing diked area, no additional cleanup is proposed at this time.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature	<i>Jimmy D. Carlile</i>	OIL CONSERVATION DIVISION	
Printed Name:	Jimmy D. Carlile	Approved by District <i>John</i> ENVIRONMENTAL ENGINEER	
Title:	Reg. Affairs. Coord.	Approval Date:	10.29.07
E-mail Address:	jimmyc@forl.com	Expiration Date:	12.31.07
Date:	10/29/07	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432 687-1777		

* Attach Additional Sheets If Necessary

RP# 1637