

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor
Joanna Prukop
Cabinet Secretary

Mark E. Fesmire, P.E.
Director
Oil Conservation Division

ULS-T-R O-8-17-35 PI Well No. 30-025-35948 Property DIRT DEVIL 8

Well No. 1

Picase o	-103. Report of Plugging has been approved as to plugging of the Well Bore. Liability under bond is retained until an D representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations, theck each item in the space provided to indicate that the work has been accomplished and the location is ready for final
inspecti	on.
/	OLD BIRY AIC SOUNDS
\mathcal{L}	1. All pits have been remediated, filled and leveled.
	1. All pits have been remediated, filled and leveled. 2. Rat hole and ceilar bave been filled and leveled. OLD Btry Site South of Marker Conduit sticking out of ground, Plasoft
	3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanenty welded, stamped or otherwise engraved into the metal marker.)
	 4. The location has been loveled as nearly as possible to original top ground contour and has bee cleared of all junk and equipment. 5. The dead men and tie downs have been cut and removed. 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have bee remediated, leveled and cleared of all junk & equipment.
۷,	5. The dead men and tie downs have been cut and removed.
_	6. If a one well lease or last remaining well on lease, the buttery and burn pit locations have bee remediated, leveled and cleared of all junk & equipment.
_/	7. All environmental concerns have been addressed as per OCD quidelines.
	The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned Wells have been inspected.
,	When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter. To us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Name Luran Sodugue

Title_/