Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Ave , Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S St. Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
May 27, 2004

WELL API NO.	30-025-12788
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	HOBBS SWD System
8. Well Number	E-15
9. OGRID Number	
10. Pool name or Wildcat	SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other SWD WELL
2. Name of Operator: RICE OPERATING COMPANY
3. Address of Operator: 122 W. TAYLOR ST., HOBBS, NM 88240
4. Well Location
   Unit Letter E : 1650 feet from the NORTH line and 840 feet from the WEST line
   Section 15 Township 19S Range 38E NMPM County LEA

11. Elevation *(Show whether DR, RKB, RT, GR, etc.)* 3611' DF

Pit or Below-grade Tank Application ☐ or Closure ☒

Pit type: NONE Depth to Groundwater: 60 ft Distance from nearest fresh water well: 2400 ft

Distance from nearest surface water: >1000 ft Pit Liner Thickness: n/a mil Below-Grade Tank: Volume 800 bbls

Construction Material: REDWOOD

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	P AND A ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPLETION ☐	CASING/CEMENT JOB ☐	
OTHER: ☐		OTHER: **WELL SITE ABANDONMENT & SURFACE RECLAMATION** ☒	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach well bore diagram of proposed completion or recompletion.

The SWD well at this facility was plugged and abandoned on February 6, 2002.
Closure activities at the site began on June 25, 2007 in accordance with the NMOCD-approved Corrective Action Plan submitted by the consultants of Arcadis of Midland, Texas. Excavations at the former redwood tank and emergency pit sites were lined with a compacted clay barrier, backfilled with compacted, blended soils, and capped with quality topsoil. The facility's caliche pad was removed and the site was covered with quality soil and planted with a seed mixture of native vegetation.

The enclosed report from Arcadis provides additional information and documentation of the closure work completed at this facility.

DEC 2007 Received Hobbs OCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief. **I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☒.**

SIGNATURE Kristin Farris Pope TITLE Project Scientist DATE 12-13-07
Type or print name KRISTIN FARRIS POPE E-mail address: kpope@riceswd.com Telephone No. (505) 393-9174

For State Use Only

APPROVED BY: Chris Williams TITLE District Supervisor DATE 12/18/07
Conditions of Approval (if any): Attach final closure lab results. CW