

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company	CHESAPEAKE OPERATING, INC.	Contact	BRADLEY BLEVINS
Address	P. O. BOX 190 HOBBS, NM 88241	Telephone No.	505-391-1462
Facility Name	Trinity Burrus Abo Unit #26	Facility Type	Producing Well
Surface Owner	Burrus	Mineral Owner	
		Lease No.	

**LOCATION OF RELEASE** API# 30025359850000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	27	12S	38E					LEA

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	PRODUCED WATER	Volume of Release	160 BBLS	Volume Recovered	30 BBLS
Source of Release	WATER PUMP FAILURE	Date and Hour of Occurrence	1/18/07 7:00 P.M.	Date and Hour of Discovery	1/19/07 9:00 A.M.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
		PAT CAPERTON			
By Whom?	BRADLEY BLEVINS	Date and Hour 1/19/07 10:00 A.M.			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

**RECEIVED**

JAN 11 2008

**HOBBS OGD**

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
WATER PUMP FAILURE RELEASING 160 BBLS OF PRODUCED WATER TO LOCATION SURFACE. VACCUM TRUCKS  
DISPATCHED TO RECOVER AS MUCH FLUID AS POSSIBLE.

Describe Area Affected and Cleanup Action Taken.\*  
30 BBLS OF PRODUCED WATER WAS RECOVERED. SOIL REMEDIATION ACTIVITIES COMMENCED. SOIL WAS  
EXCAVATED, FINAL SAMPLES COLLECTED AND ANALYZED, AND BACKFILLED AFTER VERBAL APPROVAL ON FEB. 1,  
2007 FROM CHRIS WILLIAMS OF THE NMOCD. LAB DATA ATTACHED.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.


**OIL CONSERVATION DIVISION**

Signature: <i>Cliff P. Brunson</i> for Chesapeake Operating, Inc.	Approved by District Supervisor: <i>Chris Williams</i>	
Printed Name: CLIFF P. BRUNSON	Approval Date: 2/10/07	Expiration Date: 2/10/07
Title: PRESIDENT	Conditions of Approval:	
E-mail Address: CBRUNSON@BBCINTERNATIONAL.COM	Attached <input type="checkbox"/>	
Date: 1/09/08	Phone: 505-397-6388	

\* Attach Additional Sheets If Necessary

# 1217





2111 Beechwood, Abilene, TX 79603 101 East Marland, Hobbs, NM 88240  
(915) 673-7001 Fax (915) 673-7020 (505) 393-2326 Fax (505) 393-2478

## CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

Page 1 of 1

[illegible]

† Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476.