Form 3160-5 (April 2004) 1.

## UNITED STATES DEPARTMENT OF THE INTERIOR DCD-HORBS BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires March 31, 2007

5. Lease Serial No

1		
11 0	A 4 0 7 4 1	٨
111.	048741-	м

SUNDRY NOTICES AND REPORTS ON WELLS			LC 048741 - A 6 If Indian, Allottee or Tribe Name		
Do not use this form for abandoned well. Use For	n 3160-3 (APD) for s	uch proposals.		o mindian,	Anotice of Thoe Name
SUBMIT IN TRIPLICATE -	- Land of the land	n everse side		7. If Unit or	CA/Agreement, Name and/or No.
1. Type of Well Gas Well Other FEB 1 8 2008			· ·	8. Well Name and No. EUNICE MONUMENT 123	
2. Name of Operator XTO Energy Inc.		BBS OCD		SOUTH UNIT 9 API Well No.	
		<ul><li>b. Phone No (include at 432-620-6740</li></ul>	rea code)	30-025-29957	
200 LORAINE, STE, 800 MIDLAND, 4. Location of Well (Footage, Sec., T, R., M., or Survey I	432-620-6740			d Pool, or Exploratory Area DNUMENT; GRAYBURG	
660 Feet from the South line and 2287 Feet from the West line; Unit				SAN ANDRES	
Letter N. Section 25, T-20-S, R-36-E, NMPM, Lea County, New Mexico				11. County or Parish, State	
12. CHECK APPROPRIATE	POV(ES) TO INDIC	PATE NATURE OF	NOTICE DED	LEA	THER DATA
, , , , , , , , , , , , , , , , , , ,	BOX(E3) TO INDIC		•	JKI, UK U	THER DATA
TYPE OF SUBMISSION		1 Y	PE OF ACTION		
Notice of Intent	Acidize	Deepen	Production	(Start/Resume)	Water Shut-Off
X Subsequent Report	Alter Casing	Fracture Treat	Reclamatio	n	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplet	e	X Other <u>Extend TA</u>
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporaril	y Abandon	Status
	Convert to Injection	Plug Back Water Disposal			
testing has been completed. Final Abandonment N determined that the final site is ready for final inspect MIT Chart Attached. Test was per	ction)		ciuding reciamatio	n, nave been	completed, and the operator has
XTO is currently evaluating this Status until this evaluation can		time would like	and the second s	And the land of th	
SEE ATTACI CONDITION		~ u . u .			ED FOR RECORD  EB 1 3 2008  LES BABYAK ROLEUM ENGINEER
After_ or plan	<u>5/13/e8</u> the s s to P & A must I	well must be or be submitted.	nline	PETE	LES BABYAK ROLEUM ENGINEER
<ol> <li>I hereby certify that the foregoing is true and correct Name (Printed/Typed)</li> </ol>		Title	Charles and the same	Literature Action	The state of the s
Kristy Ward		Regula	tory Analyst		
Trusty Ward		Date 01/31/08			
	SPACE FOR FEDER				
Approved by	OC DISTRICT SUF	TERV SÖK/GENERA	L MANAGER		Date in 20 2000
Conditions of exproval, if any, are attached Approval of certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations the	those rights in the subject	ant or Office lease			

Title 18 U S.C Section 1001, and Title 43 U S C Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



## United States Department of the Interior BUREAU OF LAND MANAGEMENT Carlsbad Field Office



620 E. Greene St. Carlsbad, New Mexico 88220 Tel. (505) 234-597 Fax (505) 234-5927

February 12, 2008

XTO Energy Inc. 200 Loraine, STE. 800 Midland, TX. 79701

RE: Eunice Monument South Unit Wells: 103,123,202,210,335,371,415,418,854,876,878,886,896 and 917

## Gentlemen:

Our records indicate that the above well is Shut-in (SI) or Temporarily Abandoned (TA). The Bureau of Land Management (BLM) and Minerals Management Service (MMS) definition of a shut-in well is a completion that is physically and mechanically capable of production in paying quantities or capable of service use. The definition of a temporarily abandoned well is a completion that is not capable of production in paying quantities but which may have value as a service completion. According to our records the well referenced above has been shut-in for 6 months or longer. 43 CFR 3162.3-4 (C) requires that wells incapable of production in paying quantities be promptly plugged and abandoned and requires approval for any well temporarily abandoned for more than 30 days.

Therefore your Sundry Notices are being accepted for record purposes and will not be approved. You need to submit a plan for these wells within in 90 days and do one of the following with each well, at a rate of 2 wells per month.

- 1. Return the well to production or beneficial use.
- 2. Submit notice of intent to plug and abandon.

## Corrective Action to be Completed as follows:

If you decide to **plug and abandon** the well, submit a Sundry Notice (form 3160-5, original and 5 copies) describe the proposed plugging program.

If you decide to return the well to production, submit a Sundry Notice (form 3160-5, original and 5 copies) of intent. Include the date you anticipated the well being placed back in service. 43 CFR 3162.4-1(c) also requires you to notify the Authorized officer, not later than the fifth business day after production is resumed for any well which has been off production for more than 90 days, the date on which such production was resumed. Notification may be by letter or Sundry Notice, or orally followed by letter or Sundry Notice.

If the well is to be used for **beneficial purposes**, submit a Sundry Notice (Form 3160-5, original and 5 copies) include information concerning future use. A brief description of your proposed plans and economic feasibility and an anticipated date for placing the well in beneficial use will suffice. Beneficial use includes, but is not limited to, recompilation to other horizons, conversion to injection for secondary or enhanced recovery, and saltwater disposal or injection.