Submit 3 Copies To Appropriate District Office District I	State of New Energy, Minerals and	F	orm C-103 May 27, 2004			
1625 N. French Dr., Hobbs, NM 88240 District II		una unante a co an attracto contraco.	WELL API NO. 30-025-38626			
1301 W. Grand Ave., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	OIL CONSERVAT 1220 South St.	Francis Dr.	5. Indicate Type of Lease STATE X FEE			
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505		R 3 1 2008	6. State Oil & Gas Lease No. E-5837			
SUNDRY NOTI (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC	7. Lease Name or Unit Agreer Swan 23 State Com	nent Name				
PROPOSALS ) 1. Type of Well: Oil Well	8. Well Number					
2. Name of Operator Mewbourne Oil Company	9. OGRID Number 14744					
3. Address of Operator PO Box 5270 Hobbs, NM 88240			10. Pool name or Wildcat Pearl Morrow North (Gas)	-		
4. Well Location Unit Letter O : 710	4. Well Location Unit Letter O : 710 feet from the S line and1980 feet from theE line					
Section $\overline{23}$ $\overline{}$	Township 19S		NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3728' GL						
Pit or Below-grade Tank Application 🗌 o						
Pit typeDepth to Groundwa						
Pit Liner Thickness: mil	Below-Grade Tank: Volume		nstruction Material			
12. Check A	Appropriate Box to Indica	te Nature of Notice,	Report or Other Data			
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPORT OF	:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORI		CASING 🗌		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LING OPNS. PAND A			
PULL OR ALTER CASING		CASING/CEMENT	ЈОВ 🛛			
OTHER:		OTHER:				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.						

03/08/08 Spud 17  $\frac{1}{2}$ " hole. Ran 515' 13  $\frac{3}{8}$ " 48# H40 ST&C csg. Cemented with 100 sks BJ Lite Class "C" (35:65:6) with additives. Mixed @ 12.5 #/g w/ 1.98 yd. Tail with 400 sks Class C with 2% CaCl2. Mixed @ 14.8 #/g w/ 1.34 yd. Circ 90 sks to pits. WOC 18 hrs. At 5:30 pm on 03/09/08, tested 13  $\frac{3}{8}$ " casing to 1250# for 30 minutes, held OK. Drilled out with 12  $\frac{1}{4}$ " bit.

03/24/08 TD'ed 12 <sup>1</sup>/<sub>4</sub>" hole @ 5400' Ran 5400' 9 <sup>3</sup>/<sub>8</sub>" 40# N80/H/K55 LT&C Csg. Cemented with 1650 sks BJ Lite Class "C" (35:65:6) with additives. Mixed @ 12.5 #/g w/ 2.05 yd. Tail with 400 sks Class "C" neat. Mixed @ 14.8 #/g w/ 1.32 yd. Circ 110 sks to pit. WOC 18 hrs. Tested BOPE to 5000# & annular to 2500#. At 10:45 am on 03/27/08, tested casing to 1500# for 30 minutes, held OK. Tested formation to 12.5 MWE. Charts and schematic attached. Drilled out with 8 <sup>3</sup>/<sub>4</sub>" bit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .

SIGNATURE Jetie Fathan	TITLE_Hobbs Regulatory	DATE03/28/08
Type or print name Jackie Lathan For State Use Only	E-mail address jlathan@mewbourne.com	Telephone No. 505-393-5905
APPROVED BY:	TITLE Geologist	DAPER 0 8 2008



and the second second



Company MEW BOU RUE	Date 3/26/08			
Lease SWAN "23" ST Com #1	County LEA CS. N.M.			
$\hat{D} = I + c$	Plug & Drill Pipe Size 22. 11 4 1/2 AV			

## Accumulator Function Test - OO&GO#2

To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)

- Make sure all rams and annular are open and if applicable HCR is closed. 2700
- Ensure accumulator is pumped up to working pressure! (Shut off all pumps)
- 1. Open HCR Valve. (If applicable)
- 2. Close annular.
- 3. Close all pipe rams.
- 4. Open one set of the pipe rams to simulate closing the blind ram.
- 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).
- 6. Record remaining pressure 1600 psi. Test Fails if pressure is lower than required.
  - a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system}
- 7. If annular is closed, open it at this time and close HCR.

## To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:
  a. {800 psi for a 1500 psi system}
  b. {1100 psi for 2000 and 3000 psi system}
  - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
  - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
  - 3. Record pressure drop 1000 psi. Test fails if pressure drops below minimum.
- Minimum: a. {700 psi for a 1500 psi system } b. {900 psi for a 2000 & 3000 psi system}

## To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
  - 1. Open the HCR valve, {if applicable}
  - 2. Close annular
  - 3. With pumps only, time how long it takes to regain the required manifold pressure.
  - 4. Record elapsed time 1:20 min Test fails if it takes over 2 minutes.
    - a. {950 psi for a 1500 psi system} h. (1200 psi for a 2000 & 3000 psi system)
- 6

	WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM			INVOICE		
	Grand		ID GAS SEPA		B and the second s	8421
Company MEW BOURNE DIL			Date	3/26/0	F_Start Time 4:00	am 🔀 pm
Lease SWAN "23" ST	Com #	(		· · · · · · · · · · · · · · · · · · ·	County LEA	State
Company Man LyDU SIMMONS					· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·
Wellhead Vendor			_ Tester,	KZNNY 1	Kirkpiatrick	
Drlg. Contractor <u>Patterson Uts</u>					Rig #^	47
Tool Pusher <u>Lenge</u>		·				v vii
Plug Type		P	lug Size	// '	Drill Pipe Size4	2 APT
Casing Valve Opened				_ Check Valve Op	pen	I
Check Valve 11	26 2 4 4 5 5 7 7 7 7 7 7 7 7 7 7 7 7 7	LOW PSI	HIGH PSI	24, 22, 21, 21,	23 18 20 REMARKS	
1 9,13, 25, 26,6	3/12	250				
2 10, 1, 2, 5, 13	3/10	250	5000			
3 11, 13, 3, 4, 5	3/10	250	5000			
4 15,11,7	3/10	250	2500			
5 12 11,7	3/10	250	5000			
6 12,11,8	3/10	250	5000			
7 16	3/10	250	5000			,
8 17	3/10	250	5000	-	· · · · · · · · · · · · · · · · · · ·	
9 19	3/10	250	5000			
	~ 1 ~	· · · · · · · · · · · · · · · · · · ·				
				7		
			1 1: -	1		
			sta [1-9	light and t	· · · · · · · · · · · · · · · · · · ·	
8 HR@ 1000 0 100	0				SUB TOTAL _/ O	8200
HR@					TAX	58-16
Mileage 5 2 @ / 42 5 2	ę."					7016
MASTER PRINTERS 575 396 3661					IUIAL	(

MASTER PRINTERS 575 396 3661

*y* \*