



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**

Cabinet Secretary

**Mark E. Fesmire, P.E.**

Director

**Oil Conservation Division**

**\*Response Required – Deadline Enclosed\***

*Field Inspection Program*

*"Preserving the Integrity of Our Environment"*

19-May-08

**ENERGEN RESOURCES CORPORATION**  
**3300 N. A. ST BLDG. 4 STE 100**  
**MIDLAND TX 79701**

**LETTER OF VIOLATION - Inspection**

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

***INSPECTION DETAIL SECTION***

<b>LAMBIRTH No.004</b>				<b>O-31-5S-33E</b>	<b>30-041-20457-00-00</b>	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/15/2008	Routine/Periodic	Maxey Brown	Yes	No	8/18/2008	iMGB0813635863
<b>Violations</b>						
Absent Well Identification Signs (Rule 103)						
<b>Comments on Inspection:</b> NO Well Sign (Rule 103). NEED TO INSTALL WELL SIGN. (PUMPING UNIT ON WELL). THIS IS 1ST LETTER OF NON-COMPLIANCE. MGB.						
<b>LAMBIRTH A No.001</b>				<b>J-31-5S-33E</b>	<b>30-041-20471-00-00</b>	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/15/2008	Routine/Periodic	Maxey Brown	Yes	No	8/18/2008	iMGB0813635088
<b>Violations</b>						
Absent Well Identification Signs (Rule 103)						
<b>Comments on Inspection:</b> NO Well Sign (Rule 103). NEED TO INSTALL WELL SIGN. THIS 1ST LETTER OF NON-COMPLIANCE. MGB.						

**LAMBIRTH A No.003**

N-31-5S-33E

**30-041-20484-00-00**

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/15/2008	Routine/Periodic	Maxey Brown	Yes	No	8/18/2008	iMGB0813636568
<b>Violations</b> Absent Well Identification Signs (Rule 103)						
<b>Comments on Inspection:</b> Well Sign (Rule 103). NEED TO INSTALL WELL SIGN WITH CORRECT OPERATOR AND API #. THIS IS 1ST LETTER OF NON-COMPLIANCE. MGB.						

**LAMBIRTH A No.004**


A-31-5S-33E

**30-041-20506-00-00**

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/15/2008	Routine/Periodic	Maxey Brown	Yes	No	8/18/2008	iMGB0813633040
<b>Violations</b> Absent Well Identification Signs (Rule 103) Idle well (Rule 201)						
<b>Comments on Inspection:</b> EXPIRED T/A STATUS RULE 203. NEED TO RETURN TO PROD, T/A, OR P/A WELL. ALSO NEED TO INSTALL WELL SIGN, RULE 103. THIS IS 1ST LETTER OF NON-COMPLIANCE. MGB.						

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,

**COMPLIANCE OFFICER**

Hobbs OCD District Office

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data  
\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD  
OIL CONSERVATION DIVISION  
1625 N FRENCH DRIVE  
HOBBS NM 88240

ENERGEN RESOURCES CORPORATION  
3300 N. A. ST BLDG. 4 STE 100  
MIDLAND TX 79701



HASLER

014H15215335

**\$0.420**

05/19/2008

Mailed From 88240

US POSTAGE