

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals & Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P. O. Box 1980, Hobbs, NM 88240

DISTRICT II

P. O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088

Santa Fe, NM 87504-2088

WELL API NO.

30-025-33269

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-2148

7. Lease Name or Unit Agreement Name

Caprock Maljamar Unit

8. Well No.

191

9. Pool name or Wildcat

Maljamar Grayburg San Andres

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1 Type of Well:

OIL ☒

GAS ☐

WELL ☐

OTHER

2. Name of Operator

The Wiser Oil Company

3. Address of Operator

P.O. Box 2568 Hobbs, New Mexico 88241 (505) 392-9797

4. Well Location

Unit Letter G : 2474 Feet From The North Line and 2472 Feet From The East Line

Section 19 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4100' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Run freepoint, recover fish & repair ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/01/03 MIRU Eunice Well Service. POH w/rods & pump. Drop standing valve. Pressure test tbg. - hole in tbg. ND WH. RU BOP. Tbg. stuck. RU Rotary WL. Ran freepoint @ 3980' - 100% free & 3985' - stuck. Chemical cut 2-7/8" tbg. @ 3958'. POH w/137 1/2 jts. 2-7/8" tbg.

7/02/03 RIH w/4-5/8" overshot, grapple, bumper sub & Johnson jars on 2-7/8" tbg. Caught fish @ 3962'. Jar fish to 3938'. Could not jar fish loose.

7/03/03 Jar fish @ 3962'. Could not jar loose. Release from fish. POH w/2-7/8" tbg. & DC's. LD tools. RIH w/4-1/2" cutrite shoe, 4-1/2" wash pipe, bumper sub, Johnson jars & DC's on 2-7/8" tbg. to 2500'.

7/07/03 Tag fish @ 3962'. Mill on fish.

7/08/03 Mill on fish to 3967'. Fish fell downhole. RIH w/tbg. to 4210'. Fish would not go further. POH w/tools & tbg.

7/09/03 RIH & caught fish. POH w/fish & tbg. Recovered all fish. RIH w/2-7/8" tbg. ND BOP. NU WH.

7/10/03 RIH w/rods & 2-1/2" x 1-1/2" x 20' pump. Hung well on. Left pumping to Battery. RDMO.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner
TYPE OR PRINT NAME Mary Jo Turner

TITLE Production Tech II

DATE October 1, 2003

TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY

Harry W. Wink

OC FIELD REPRESENTATIVE II/STAFF MANAGER

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY: