

Submit 2 Copies To Appropriate District Office State of New Mexico Office Minerals and Natural Resources	Form C-103 October 25, 2007
District I Ellergy, Witherars and Watural Resources	WELL API NO.
District II	30-025-27568
1301 W. Grand Ave., Artesia, NM 88219 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name EAGLE
PROPOSALS.) 1. Type of Well: ☐Oil Well ☑Gas Well ☑ Other P&A'd	8. Well Number 1
2. Name of Operator	9. OGRID Number
Southwest Royalties, Inc.	021355
3. Address of Operator	10. Pool name or Wildcat
6 Desta Drive, Ste 2100, Midland, TX 79705	Jalmat Tan Vates - 7 Ros
4. Well Location	
Unit Letter J: 2310et from the Sline and 1650 from the Eine	
Section 36 Township 25S Rnge 36E NMPM Lea County NM	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 2981' GR	*********
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF: C
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	LLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	JOB 🔲
OTHER: Discretion Stready for OCD inspection after P&A	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed.	ved. (Poured onsite concrete bases do not have
to be removed.)	
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from	
non-retrieved flow lines and pipelines.	The rain mands have been removed from
1 1	$\alpha K'$.
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one	
inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
SIGNATURE Common forward TITLE Operations A	DATE 7/14/09
Operations A	DATEDATE
TYPE OR PRINT NAMEDawn M. Howard E-MAIL: dhoward@claytonwillian	ns.com PHONE: 432/688-3267
For State Use Only	<u> </u>
APPROVED BY: TITLE TITLE	DATE
Conditions of Approval (if any):	