

RECEIVED

Submit 2 Copies To Appropriate District  
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM  
87505

JUL 29 2008

State of New Mexico

Energy, Minerals and Natural Resources

HOBBS OGD

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-103

October 25, 2007

WELL API NO. 30-025-32597 /
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-3406-1
7. Lease Name or Unit Agreement Name Central EK Queen Unit /
8. Well Number Tract 11 #2 /
9. OGRID Number 20497 /
10. Pool name or Wildcat EK-Yates-SR-Queen /

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: <input type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/> Injection	
2. Name of Operator Seely Oil Company /	
3. Address of Operator 815 W. 10 <sup>th</sup> St., Ft. Worth, TX 76102	
4. Well Location Unit Letter A: 660 feet from the North line and 660 feet from the East line / Section 17 Township 18S Range 34E NMPM Lea County, NM	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

This well has been plugged and abandoned.

Seely Oil Company respectfully requests permission to remove the caliche on the location and adjoining lease road. The materials will be used to repair the main lease road or to build the next location that Seely drills.

SIGNATURE David L. Henderson TITLE: Executive Vice President DATE: 7/21/2008

TYPE OR PRINT NAME: David L. Henderson E-MAIL: [dhenderson@seelyoil.com](mailto:dhenderson@seelyoil.com) PHONE: 817-332-1377

For State Use Only

APPROVED BY: Chris Williams TITLE: OGD DISTRICT SUPERVISOR/GENERAL MANAGER DATE: JUL 29 2008  
Conditions of Approval (if any):