



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Response Required – Deadline Enclosed

Field Inspection Program

"Preserving the Integrity of Our Environment"

05-Aug-08

FULFER OIL & CATTLE LLC

P.O. BOX 1224

JAL NM 88252

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

THOMAS No.001				L-17-24S-37E	30-025-25404-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
08/05/2008	Routine/Periodic	Mark Whitaker	Yes	No	10/13/2008	iMAW0821845196
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection: Well sign not legible (Rule 103). NEED TO REPLACE WELL SIGN. 1st letter of non-compliance. MW						
THOMAS No.002				K-17-24S-37E	30-025-25658-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
08/05/2008	Routine/Periodic	Mark Whitaker	Yes	No	10/13/2008	iMAW0821844665
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection: No well Sign (Rule 103). Surplus chemical drums at battery and no sign. NEED TO INSTALL WELL SIGN AT WELL. ALSO NEED TO REMOVE SURPLUS CHEMICAL DRUMS AT BATTERY AND INSTALL SIGN AT BATTERY. 1st letter of non-compliance. MW						

THOMAS No.003

J-17-24S-37E

30-025-25831-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
08/05/2008	Routine/Periodic	Mark Whitaker	Yes	No	10/13/2008	iMAW0821844222

Violations

Absent Well Identification Signs (Rule 103)

Comments on Inspection: Well sign (Rule 103). Well sign not legible. NEED TO REPLACE WELL SIGN. 1st letter of non-compliance. MW

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,



COMPLIANCE OFFICER


Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240

**FIRST
CLASS**



HASLER
017H15554612
\$0.420
08/06/2008
Mailed From 88240
US POSTAGE

FULFER OIL & CATTLE LLC
PO BOX 1224
JAL, NM 88252