

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Form C-103
May 27, 2004

RECEIVED

OIL CONSERVATION DIVISION
JUL 29 2008
20 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

WELL API NO. 30-025-37382
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1431
7. Lease Name or Unit Agreement Name: SUNFLOWER 28 STATE
8. Well Number 2
9. OGRID Number 778
10. Pool name or Wildcat CANYON
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4064
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type <u>NA</u> Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator

BP AMERICA PRODUCTION COMPANY

3. Address of Operator

501 WESTLAKE PARK BLVD, RM 6.128 WL-1; HOUSTON, TX 77079

4. Well Location

Unit Letter M: 690 feet from the South line and 1160 feet from the West line

Section 28 Township 17S Range 34E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4064

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Recomp. to Canyon Formation, Perf & Acidize ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

The Sunflower 28 State #2 was given an NOV for "failing MIT" due to pressure being on the tubing-casing annulus. On 4/2/2008, BP America Production Company set CIBP at 13,074'. Perf intervals 13124-126, 13150-155, 13272-274 were covered w/40' of cmt dumped on plug. Checked csg/wellhead for press, bled off.

BP recompleted uphole and perfed the Canyon formation on 5/6/08 at the following intervals: 11,564'-570' and 11,579'-582' w/2/spf, 120 degree phasing using 4" casing gun (22 holes). On 5/12/08, BP acidized Canyon perfs 11,564-11,582' w/1000 gals 15% NE/FE HCl @ 2.0 BPM 5000 psi. Frac and test information will be reported on subsequent C-103, once procedure is done.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Deann Smyers TITLE REGULATORY STAFF ASSISTANT DATE 7/07/2008

Type or print name DEANN SMYERS

E-mail address: smyersod@bp.com

Telephone No. 281-366-4395

For State Use Only

APPROVED BY Chris Williams TITLE OC DISTRICT SUPERVISOR/GENERAL MANAGER DATE AUG 12 2008

Conditions of Approval, if any:

2A Vacuum Morrow